DAMAGEGENX

Multi-Vehicle Damage Assessment Platform

Vehicle Inspection Report

Deep Learning · IoT Sensor Fusion · Hidden-Damage Risk Prediction

Inspection ID	INS-111019
Generated on	05 Oct 2026 · 11:10 UTC
Vehicle Type	Bike
Prepared by	DamageGenX System

1. Damage Summary

Dominant Damage	Scratch
Fused Severity	7/100 · Minor
Total Detections	1
Views Analyzed	3 / 5
Vehicle Type	Bike
Primary Component	Front Bumper

2. IoT Sensor Data

Impact Force	3.5 G
Rotation	45 °/s
GPS Latitude	16.353438
GPS Longitude	81.042167

3. Hidden-Damage Risk

LOW

Risk Score: 23%

Recommendation: No immediate hidden damage concern.

Note: Hidden-damage output is a risk estimate, not a direct detection of internal damage.

4. Repair Recommendation & Cost

Recommended Action	REPAINT
Component	Front Bumper
Description	Surface repainting required.

Priority	Minor

Estimated Cost Range: INR 4,075 – 5,993

5. Annotated Views



Front



Left



Rear

6. Evidence Integrity

Front	EV-5EC59D6270 · sha256:4ad5244cb6e1bf4d…
Left	EV-5436369E3F · sha256:6985453809989f7b…
Rear	EV-6BD237AF49 · sha256:a676c72a9a9412ca…

Disclaimer

This report is generated by DamageGenX, an AI-assisted vehicle inspection platform. Detected damage, severity estimation, hidden-damage risk, and cost estimates are algorithmic outputs and may not be fully accurate. This document does not replace professional mechanical inspection or a formal repair quotation.