Vehicle Damage Assessment Report

Generated: 2026-10-05T03:03:34.371523 UTC

1. Damage Summary
View: front | Damages: 0 | Severity: none
View: left | Damages: 0 | Severity: none
View: rear | Damages: 1 | Severity: minor

2. Fusion Result
Dominant: scratch
Severity score: 0.067

3. Sensor Data
Impact (G): 1.9
Rotation (deg/s): 42

4. Hidden Damage Risk
Level: low (score=0.163)
No immediate hidden damage concern.

5. Repair Recommendation
Action: repaint
Surface repainting required.

6. Estimated Cost
INR 14556 - 21406

7. Evidence Integrity
front: EV-06ACC1CED8 · sha256:4ad5244cb6e1bf4d…
left: EV-8A7B341D2F · sha256:6985453809989f7b…
rear: EV-C285B4FC86 · sha256:a676c72a9a9412ca…

8. Vehicle Information
Vehicle Type: Sedan

9. Damage Severity Score
7/100 — Minor