
Rotational speed [rpm]
Power [W]
Tool wear [min]
Temp_diff [K]
Torque [Nm]
Overstrain_ratio
Air temperature [K]
Overstrain [minNm]
Process temperature [K]
Type_M
Type_L
Type_H
0
5
SHAP value (impact on model output)
High
Feature value
Low