

MERIDIAN HEAT TRANSFER SYSTEMS - SERVICE BULLETIN

Document MHT-PB-2026-25 | Issued 20-Aug-2026 | Supplementary to MHT-PB-2026-11

Bulletin reference:	MHT-PB-2026-25
Issue date:	20-Aug-2026
Applies to:	HE-303
Equipment class:	Shell and Tube Heat Exchanger
Component:	HE-3xx series
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements MHT-PB-2026-11, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for HE-303. It does not revise any part number, material or rating published in MHT-PB-2026-11, which remains the controlling document.

2. RECOMMENDED APPROACH TEMPERATURE ALARM THRESHOLD

For HE-303, Meridian Heat Transfer Systems recommends a approach temperature alarm threshold of 8 degrees C. A sustained approach above this value for 72 hours indicates progressive fouling.

3. TREND REVIEW INTERVAL

Trend review interval for HE-303 is specified as weekly. Values beyond monthly are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for HE-303 with Section 2 at the next scheduling review. No immediate shutdown action is required.