

Rosli Ahmad

Subject: ASJ
Start: 2015/12/01 (火) 11:00
End: 2015/12/01 (火) 12:30
Recurrence: (none)
Organizer: Rosli Ahmad

Maruwa: Rosli, Mr. Siva (QA)
ASJ: Ms. Sun, Mr. Syafiq, Mr. Penny

876M (1206) 1st break not straight

1st break in bar type in magazine clearly seen edge chip slit cause 1st breaking not straight. Mr. Siva explained root cause of 1,000 shoot mold cleaning. Operator was not clean cause ceramic dust accumulation on shader slit and cause shallow slit on that point. Countermeasure by involve QA to re-inspec and approve 1,000 soot sample by operator.

4 lots NG ASJ lots (200pcs/ASJ lot) and NG bar been remove manually from magazine. Even though it's within the spec ASJ not risk as they had customer claim before. We expected 200-300pcs might need to replace and will be inform by Mr. Penny.

ASJ also newly found same quality issue wit 1598M (0805) with ASJ 2 lots

7910M Dec 300K

ASJ earlier forecast was 586Kpcs, but latest request down to 300Kpcs. Ms. Sun accepted shipment 286K on 30-Dec (ETA ASJ 31-Dec)

ASJ & Ralec Audit

Ralec & ASJ cancel audit on 15-Dec. Maruwa been invited to ASJ for discussion with Mr. Justin QA Director about Ralec quality issue.

Others Issue

1. 7910M 2nd sample commercial value rank $\pm 1,600$ pcs for further test to Mr. Syafiq. ETD Maruwa 10-Dec (sample form issued)
2. 7910M 200pcs sample angle widen spec to 0.1 tested and result was good. So ASJ accept 7910M new angle spec 0.1
3. 7910M debris (ship breaking) countermeasure lot CM03 40Kpcs ETD Maruwa 19-Nov, just start to in-put. Result after 2weeks.
4. Mr. Syafiq request 874M 6Kpcs for Dummy NG (test print purpose). Collect from visual inspection, ETD Maruwa on 17-Dec.
5. 9-17'Jan Ms Sun holiday (Japan)
6. Mr. Syafiq request lot no. on bundle. To follow Yageo method additional sticker on bundle. If ASJ accept Jan-16 start shipment.