

Customer: PANASONIC JAPAN		Date: 29-Aug-17	Time: 10:00
Participant From Maruwa		Participant From Organizer	Report To
1. Mr Siva	MMSB QA	1. Mr Yoshida	QA
2. Mr Matsumoto	JP MW SALES	2. Mr Sakai	QA
3. Mr Mori	JP MARUWA	3. Ms Hamada	IQC
4.		4 Mr Okui	SQM
5.		5. Mr Ishikawa	Purchasing MGR

Agenda

Today's discussion was focus on Maruwa action item for the claims from Apr'17 ~ Aug'17

ALT8GKB - Thickness NG

Explained on the current action taken by MARUWA and Mr Yoshida requested MARUWA to link the NG whether it's due to casting machine slip or dirty. Request to create FTA for the defects

Total defect found was 130pcs (0.01%) and required MARUWA to link this NG with the casting coil

Other claim items have been explained and below is the request item from PANASONIC JAPAN

MARUWA		PANASONIC JAPAN - TASK		29-08-17	
No	Complaint	Details	PIC	DATE	
1	ALT8GKB THICKNESS NG	FTA to be reviewed and include for a. Film slip b. Dirty	MR SIVA	12-09-17	
2		Analysis of return NG thickness sample Propose to study the trend for 2 main reason a. Slip b. Dirty	MR SIVA	12-09-17	
3		Thickness sensor installation schedule and operating OPL	Mr ERUAN	15-09-17	
4		IRequest review the presentation to include additional control point and link with the FTA	Mr SIVA MR THIVAKAR	05-09-17	
5		Proposal to include the thickness check at Ranking or pressing process	Mr SIVA	TBC	
6	ALT16-4TB THRU HOLE SHIFTED	Current buyoff for thru hole shifted is 8point/sheet. Requested to add in to 9 points/sheet	MR AZFAR	TBC	
7		Request to submit the Non confirming procedure	MS MARLINA	08-09-17	
8		Thru hole measurement automation - OPL & method	MR BERNARD	08-09-17	
9	ALT10-2TE DIMENSION NG	Revise 8D report to add in the cause why product can flow out	MR SIVA	05-09-17	
10	ALT2GNH WRONG INSPECTION REPORT	Request countermeasure for system error during data transfer for inspection report preparation	MR PREM MR SATYA	08-09-17	
11	ALTEG1ANSA THICKNESS RANGE BIG	Requested OPL for GR&R for measurement. Requested also to carry out daily confirmation to ensure measurement method in order	MS MARLINA MS KAVITHA	08-09-17	

Overall discussion focus on the thickness claim and Mr Yoshida requested to re-prepare the presentation
Meeting adjourned at 2:15pm

Conclusion & Opinion

Mr Sakai requested MARUWA to concentrate for the thickness claim. Since product was used in AUTOMOTIVE industries, any flow out will create a big market claim. Requested MARUWA to expedite the thickness sensor installation and would like see the functionality of it.

SUBSTRATE QUALITY MEETING

MARUWA (MALAYSIA) 基板品質打合せ

ALT-25KB (板厚厚い)

<背景> MARUWA様より4月、約7年前に使用。2回目

<目的> 今回で、懷疑、再発防止の取組を実施す

(発生状況) 詳細の調査結果

INVESTIGATION RESULT

① 調査 2017年7月17日検査。P-10 P-101X

母数 12000 X 0.01% = 120 (検査)

② MARUWA 調査結果、N/A? P-10 破り

< MARUWA 調査結果 >

発生原因不明 ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

PROPOSE TO ANALYSE AS



2017年8月29日 10:00 ~ 13:00
(MARUWA) Mr. SIVA, 森MAR 松本SYO
(Panasonic) (製) 奥井SH (調) 登川 (QA) 吉田L 貴田・徳井(記)

特別会議室

PANASONIC: MR OKUI, MR HISHIKAWA, MR YOSHIDA, MS
HAMADA, MR SAKAI

<要請事項>

1. 原因の特定 ① E-1 ② E-1 ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿
2. FTA の再整理 再提出後
3. 調査結果 対象は FTA と連動する (メカニカル)
4. センサ・取り付け口 全数保証の為、センサ取り付けのロジックを明確にする。(P-101X シフト分岐装置 アドレス換算前)
5. 作業方法 管理方法 異常発生方法 何卒確認
6. 原則口 センサ取り付け後、稼働後の監視をする。
7. 次回報告は 9/11 の頃とする。

REQUEST ITEM

1. CAUSE IDENTIFICATION
2. FTA REVIEW BACK
3. FTA MATCH WITH THE RESULT/FINDING
4. MARUWA NEED TO GURANTTE 100% FOR THICKNESS CONFIRMANCE. (ACTION SHOULD
5. SENSOR INSTALLATION - DOCUMENTAION FOR OPL, ABNORMAL FLOW, PM
6. SENSOR INSTALLTION & IN OPERATION BEFORE PANASONIC AUDIT (27/09)
7. RE-PRESENTATION FOR THE ABOVE MATTER ON 12TH/SEPT AT PANASONIC JAPAN)

No	Complaint	Details	PIC	DATE
1	ALT8GKB THICKNESS NG	FTA to be reviewed and include for a. Film slip b. Dirty	MR SIVA	12-09-17
2		Analysis of return NG thickness sample Propose to study the trend for 2 main reason a. Slip b. Dirty	MR SIVA	12-09-17
3		Thickness sensor installation schedule and operating OPL	Mr ERUAN	15-09-17
4		IRequest review the presentation to include additional control point and link with the FTA	Mr SIVA MR THIVAKAR	05-09-17
5		Proposal to include the thickness check at Ranking or pressing process	Mr SIVA	TBC
6	ALT16-4TB THRU HOLE SHIFTED	Current buyoff for thru hole shifted is 8point/sheet. Requested to add in to 9 points/sheet	MR AZFAR	TBC
7		Request to submit the Non confirming procedure	MS MARLINA	08-09-17
8		Thru hole measurement automation - OPL & method	MR BERNARD	08-09-17
9	ALT10-2TE DIMENSION NG	Revise 8D report to add in the cause why product can flow out	MR SIVA	05-09-17
10	ALT2GNH WRONG INSPECTION REPORT	Request countermeasure for system error during data transfer for inspection report preparation	MR PREM MR SATYA	08-09-17
11	ALTEG1ANSA THICKNESS RANGE BIG	Requested OPL for GR&R for measurement. Requested also to carry out daily confirmation to ensure measurement method in order	MS MARLINA MS KAVITHA	08-09-17