



出張報告書

報告先・Report To:

Datuk Anthony CEO
Mr. Ogawa MD
Mr. Sinna, Mr. Theva Directors
Mr. Rajen, Mr. Loga
Mr. Siva, Mr. Amirol QA
関連事業部・Related Dept
出張者・B/Trip Colleuge
関係者・Related Person

期間 Date 2019/7/17

出張者 Name Mr Siva

添付資料 Attachment 有 Yes 無 No

同行者 Colleuge Mr Rosli

MM-IN-RD-9100-P06-04 Rev.2

出張先 Customer	Samsung Philipines (SEMPHIL)	相手先 面談者 Attendance	Mr Tony Shum – Purchasing Manager Ms Emily – Purchasing Ms Umai – QC
出張目的 Visit Purpose	☒ 7910M – Angle (Printing shifted) ☒ 874M – Crack ☒ Others	会議フロアアップ項目 Meeting Follow-Up	☒ As attach in below table ☒ ☒

報告内容 Report

Meeting begin at 11:30AM

Topic #1 : 7910M Angle shifted

Kamaya complaint printing shifted even with R & L separated. Request Kamaya engineering to confirm below items before concluding product error

- a. Shifted mode
- b. Machine setting
- c. Failure rate
- d. Mask condition ==> actual mask buyoff

Comment from Kamaya => After changing of mask, printing is ok

MM – Requested to confirm the printing mask measurement

Further action will be taken after Kamaya submits the required info (as above)

MM also brief on the measurement method of angle. No calculation involved and measurement done by Ranking machine

Topic #2 : 874M crack

Kamaya explained still IQC detecting crack after various action

Latest detection : 874M

Failure only detected for 874M only and not for 1598M & 7910M. Request Maruwa to confirm why this can occur

IQC will continue feedback the incoing result

0

Topic #3: Reduction of COC data (Insp report)

Kamaya requesting to combine all inspection report to be one report

MM Reply : MM will submit in softcopy (pdf format) and Kamaya can printout which ever report they requires.

* Currently MM is submitting report by Lot No & mould no in hardcopy

Topic 4 : SC (Special characteristic) – How does MM controlling it?

MM ; SC was controlled for 2 character, Thickness & Slit Line

Both this character is control thru SPC and will be adjusted according to the spec.

Meeting adjourned at 1:45pm

意見・Opinion

7910M – Angle due to control of printing screen. Kamaya need to check their internal failure before concluding on the product

874M – MM need to confirm why 1598M & 7910M not crack detected in Kamaya IQC?