
Solar ESS Co. Ltd.
53 Moo 2 Tambon Nanglae, Amphoe Muang
Chiang Rai 57100, Thailand
Tel 063 151 6694, 089 632 5829
www.solaress.org · LINE: solaress1


Laundromat, Songkhla


Offline since March 2026 – check if replaced

Fix now

5 kWp*	0 kWh	–	–	–	–
PV · 5 kW inverter	PV, 1–24 Oct	kWh/kWp/day	Consumption	Bought from grid	Exported







What we found

• The Huawei inverter and dongle have been disconnected since March 2026, with a "Network Connection Error" alarm since 23 March. The plant capacity is set to 0 kWp.

• It made 590–770 kWh a month in 2025. The same laundromat also appears on SolisCloud, so the Huawei inverter may have been replaced.


What to do

1. Confirm with the owner or technician whether the Huawei inverter is still installed.

2. If it was replaced, close this plant in FusionSolar so it stops showing as faulty. If it is still installed, reconnect the dongle to Wi-Fi.

* kWp not set in FusionSolar; 5 kWp assumed.

How this plant compares (kWh/kWp per day, 1–24 Oct)



Rank 8 of 10 Huawei plants. Dashed line = expected 4.3 kWh/kWp per day.