5S
CONTROL

Convenient viewing of orders for you

Average planned time to produce an item

Workplaces: Sawing | Milling | Soldering | Deseaming | Glazing | Packing

5 hours

Actual time spent

Workplaces:

Sawing	Milling	Soldering	Deseaming	Glazing	Packing

Supply

Problems

Shift end

Repair

2 days

Orders View is a well-designed dashboard that doesn't just visualise or report, it helps you find a business solution

Identify the current stage of order execution

Time when machines are working

Idle time

# Switch between multiple orders with ease

Monitor and control your manufacturing operations in real time

View detailed analytics: operation status, responsible employee, timeline, video report

Packing

🎥 **Open Video**

Worker Wazowski
16:08:00 - 16:32:20 ✓

11:00

16:00

26.05, 07:00

Video report is a special feature to control the accuracy of performed operations

View performance forecast (based on completed orders statistics)

Workplaces

Orders	Saw	Milling	Soldering	Deseaming	Glazing	Packing	Time

Search order number

№45874

№45874

№45874

№45874

№45874

№45874

№45874

№45874

1 of 3

Current time/state

now

Performance forecast

25.05, 07 am
08 am
09 am
10 am
11 am
12 pm
13 pm
14 pm
15 pm
16 pm
26.05, 07 am
08 am
09 am
10 am
11 am
12 pm
13 pm
14 pm
15 pm
16 pm

Production time details

Execution time

No worker at the machine

Orders

Search order number 🔍

№45872

№45874

№45874

№45874

№45874

№45874

№45874

№45874

< 1 of 3 >

Workplaces

Assembling	As. Zone 1	As. Zone 2	As. Zone 3	Glazing	Packing	›

Time

25.05, **07 am**

08 am

09 am

10 am

11 am

12 pm

13 pm

14 pm

15 pm

16 pm

26.05, **07 am**

08 am

09 am

10 am

11 am

12 pm

13 pm

14 pm

15 pm

16 pm

Benefits:

01   Access real-time data for monitoring manufacturing KPIs;

02   Track employee activity in real time, enhancing accountability and transparency;

03   Increase machinery throughput by eliminating time losses;

04   Identify bottlenecks and gain actionable insights for improvement;

05   Control operations remotely without physical presence;

06   Maximize efficiency by knowing exact working and idle time.