

ENBR 202 State Transitions Table of the Initialization Fault-Report of ADARs LRU

Kristen Richmond

V1.00

Note: 4 D-Flip Flops for the States. Test will be done with help of MCU & no TEST function built-in.

Curr State		inputs	next state	main action
S00000	MCU Boot = 0		S00000	wait for MCU boot
S00000	MCU Boot = 1		S10001	activate sensor's power rail
S10001	rail Sta- bility = 0		S10001	delay for stabilization of rail
S10001	rail - stabilizing = 1		S20010	reset the sensor
S20010	the sensor reset = 0		S20010	wait for output of reset
S20010	sensor - reset = 1		S30100	MCU configuring the sensor
S30100	config - done = 0		S30100	wait for output of confirmation configuration
S30100	config - done = 1		S41000	MCU test MEMS/ sensor
S41000	test - done = 0		S41000	wait for output of test for all
S41000	test - done = 1		S50011	transfer test data to MCU sensors each bit from the barrel-in serial out shift register
S50011	data - send = 0		S50011	wait for data to be send
S50011	data - send = 1; test counter = 1		S50011	Repeat from S41000 to S50011