

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION

Requirements for Use

Nondisclosure

This document contains Protected Critical Infrastructure Information (PCII). In accordance with the provisions of the Critical Infrastructure Information Act of 2002 (the CII Act), (6 U.S.C. §671- 674), PCII is exempt from release under the Freedom of Information Act (5 U.S.C. §552) and similar State and local disclosure laws. Unauthorized release may result in criminal and administrative penalties. Safeguard and disseminate in accordance with the CII Act, the implementing Regulation at 6 C.F.R. part 29 (the Final Rule) and PCII Program requirements.

By reviewing this cover sheet and accepting the attached PCII you are agreeing not to disclose it to other individuals without following the access requirements and to abide by the guidance contained herein. Your acceptance provides immediate access only to the attached PCII. If not a PCII Authorized User, you are required to complete certification within 30 days of receipt of this information.

For Certification <https://www.cisa.gov/pcii-authorized-user-training> For Assistance pcii-assist@cisa.dhs.gov

Access

Individuals eligible to access the attached PCII must be Federal, State or local government employees or their designated contractors and must meet all the following requirements:

- Assigned to homeland security duties related to this critical infrastructure
- Demonstrate a valid need-to-know
- Sign a Non-Disclosure Agreement (except Federal employees)

Handling

Storage Store PCII in a secure container. **Do not leave this document unattended.**

Dissemination Methods:

Email Encrypt the email if possible. If unavailable, use approved email systems per PCII Program guidelines. Send PCII as a password protected attachment and provide the password in a separate email.

Mail USPS First Class mail or an equivalent. Seal the document in an opaque envelope, to prevent inadvertent opening, then place it inside a second plain outer envelope without PCII markings. Include sender's and recipient's full names and addresses on the outer envelope and add "POSTMASTER: DO NOT FORWARD. RETURN TO SENDER." below return address.

Telephone Use a secure telephone connection. If unavailable or impractical, verify the caller on other end is a PCII Authorized User and state you will discuss PCII.

Hand Delivery Authorized individuals hand carrying PCII must control it from loss or viewing throughout transit.

Reproduction Ensure this cover sheet is the first page of all reproductions containing PCII.

Destruction Destroy copies of this document when no longer required according to PCII Program procedures.

For details on access, marking, and handling requirements, see the *PCII Program Procedures Manual*.

Sanitized Products

You may create a sanitized work product using PCII. The product must not reveal any information relating to the identity of the submitting person or entity (explicitly or implicitly); is proprietary, business sensitive, or trade secret; and is otherwise not customarily in the public domain.

Derivative Products

Mark a newly created document derived from PCII with "PROTECTED CRITICAL INFRASTRUCTURE INFORMATION" in the header and footer of pages containing PCII. Mark (PCII) beside each paragraph containing PCII. Attach a PCII green cover sheet on all newly created derivative products containing PCII. Include the PCII Submission Identification Number(s) of the source document(s) on the newly created document as a footnote.

Submission Identification Number

PCII-2027

PROTECTED CRITICAL INFRASTRUCTURE INFORMATION



ABC

Enterprise Physical Security Consulting

Site Security Facility Assessment

Executive Client Report

CLIENT	Portland
SITE NAME	Clayton Jerde
ASSESSMENT ID	79
ASSESSMENT DATE	July 21, 2026
ADDRESS	742 Maple Ridge Lane, Apt 4B, Austin, TX, 78705, United States

OVERALL SECURITY SCORE

60

/ 100

RISK CLASSIFICATION

MEDIUM RISK

Table of Contents

Executive Summary	3
Property Profile	4
Geographic Crime Analysis	6
Demographic Analysis	11
Environmental Risk Analysis	15
CPTED Assessment	19
Threat Matrix	21
Business Impact Analysis	23
Nearby Infrastructure	25
Sources	28
Embedded Area Reports	30
Area Report: Area Assessment Report	30
Subarea Report: Sub Area	56
Area Report: Area Assessment Report	63
Subarea Report: Sub Area	77

Executive Summary

I

OVERALL ASSESSMENT

- (PCII) Location research was performed for 742 Maple Ridge Lane, Apt 4B, Austin, TX 78705.
- (PCII) The exact street address could not be independently verified in available public web results, so location intelligence is anchored to ZIP Code 78705 and the North University/West Campus/University of Texas central Austin context rather than to a confirmed parcel.
- (PCII) ZIP 78705 is a dense, highly transient, university-oriented area: Census Reporter lists 33,238 residents in 2.1 square miles, or about 16,056.8 people per square mile, and UnitedStatesZipCodes places the ZIP near coordinates 30.29, -97.74.
- (PCII) The area is dominated by apartments, student housing, university facilities, small commercial uses, schools, and nearby medical/institutional uses.
- (PCII) Public demographic data show a young population, low reported median household income relative to Austin and Texas, high renter occupancy, and high annual mobility, all consistent with a student-heavy district.
- (PCII) Public crime data are available through Austin Police Department CrimeViewer and the APD NIBRS Group A Offense Crimes dataset, but a validated address-level or one-/two-/three-mile extraction was not obtainable from the reviewed public pages.

S

CURRENT SECURITY POSTURE

- (PCII) Score: 60/100
- (PCII) Risk Classification: MEDIUM RISK
- (PCII) Property Type: Commercial Facility; submitted address format includes Apt 4B, suggesting possible tenant suite, apartment-style unit, or mixed-use/multitenant condition that requires verification.

A

AREA SUMMARY

- (PCII) Existing Area Report for Perimeter recorded a security score of 60 and medium risk.
- (PCII) The provided report identified perimeter-related observations and recommendations; this location intelligence report does not re-analyze those findings.; Existing Area Report for the second Perimeter entry recorded a security score of 70 and medium risk.
- (PCII) The provided area summary noted perimeter observations; this report uses the score only for aggregation and does not add new security recommendations.

Property Profile

(PCII) SITE NAME

(PCII) Clayton Jerde

(PCII) PROPERTY TYPE

(PCII) Commercial Facility; submitted address format includes Apt 4B, suggesting possible tenant suite, apartment-style unit, or mixed-use/multitenant condition that requires verification.

(PCII) PROPERTY ADDRESS

(PCII) 742 Maple Ridge Lane, Apt 4B, Austin, TX, 78705, United States

(PCII) CLIENT

(PCII) Portland

(PCII) ASSESSMENT ID

(PCII) 79

(PCII) ASSESSMENT DATE

(PCII) July 21, 2026

(PCII) ADDRESS

(PCII) 742 Maple Ridge Lane, Apt 4B, Austin, TX 78705, United States; exact public parcel/street verification not confirmed during web research.

(PCII) BUSINESS TYPE

(PCII) Business Type Code 600 supplied by user; code definition was not provided, so industry-specific risk could not be conclusively determined.

(PCII) CONSTRUCTION TYPE

(PCII) Unknown; likely central Austin urban/multifamily or mixed-use construction if the Apt 4B designation is accurate, but no building record was verified.

(PCII) ESTIMATED SQUARE FOOTAGE

(PCII) Unknown; no public square-footage record was verified for the submitted address.

(PCII) OCCUPANCY TYPE

(PCII) Commercial tenant or suite occupancy assumed from user input; possible mixed-use/multitenant occupancy due to apartment-style address designation.

(PCII) OPERATING HOURS

(PCII) Unknown; assess as potentially daytime business with after-hours vacancy unless confirmed otherwise.

(PCII) ADJACENT OCCUPANCIES

(PCII) ZIP/neighborhood context includes University of Texas facilities, student housing, apartments, small retail, restaurants, convenience uses, schools, medical/institutional uses, and dense pedestrian corridors. UT off-campus resources describe West Campus as west of UT between Guadalupe Street and Lamar Boulevard extending from Martin Luther King Jr. Boulevard to 28th Street, with parks, shops, grocery, and bus stops nearby.
(offcampus.utexas.edu(https://offcampus.utexas.edu/neighborhoods?utm_source=openai))

(PCII) ROAD ACCESS

(PCII) Central Austin/UT-area arterial access likely via Guadalupe Street, Lamar Boulevard, Martin Luther King Jr. Boulevard, Dean Keeton Street, Speedway, Duval, and local neighborhood streets; exact curb cut and frontage not verified.

Geographic Crime Analysis

1 MILE RADIUS

(PCII) VIOLENT CRIME

(PCII) Precise 1-mile count unavailable from reviewed public web pages. Expected concern categories include robbery, aggravated assault, sexual offenses, weapons violations, disorder-related assault, and alcohol/nightlife/campus-adjacent incidents. APD CrimeViewer can search by address, ZIP, crime type, and geography, but results were not extracted here because the exact address could not be verified. (austintexas.gov(<https://www.austintexas.gov/services/view-crime-statistics>))

(PCII) PROPERTY CRIME

(PCII) Precise 1-mile count unavailable. Expected primary exposure includes theft, vehicle burglary, motor vehicle theft, package theft, bicycle/scooter theft, vandalism, and burglary in student-housing/commercial corridors.

(PCII) BURGLARY

(PCII) No validated radius count available. Commercial burglary and apartment/suite intrusion risk should be assessed through APD CrimeViewer after coordinate verification.

(PCII) ROBBERY

(PCII) No validated radius count available. Robbery exposure is most relevant along pedestrian corridors, transit stops, parking areas, late-night routes, and convenience/retail nodes.

(PCII) MOTOR VEHICLE THEFT

(PCII) No validated radius count available. Vehicle theft and vehicle break-ins are material concerns in dense central Austin parking environments.

(PCII) THEFT

(PCII) No validated radius count available. Theft is assessed as the most likely crime category affecting a commercial/multitenant facility in this context.

(PCII) VANDALISM

(PCII) No validated radius count available. Vandalism/graffiti/criminal mischief risk is moderate in high-foot-traffic urban settings.

(PCII) DRUG ACTIVITY

(PCII) No validated radius count available. Drug/narcotic activity and public intoxication should be reviewed through APD non-indexed or NIBRS categories.

(PCII) OTHER

(PCII) No validated counts for homicide, weapons violations, arson, fraud, shoplifting, sex crimes, trespass, disorderly conduct, gang activity, package theft, catalytic converter theft, or commercial burglary were obtained for this radius.

2 MILE RADIUS

(PCII) VIOLENT CRIME

(PCII) Precise 2-mile count unavailable. The 2-mile environment likely includes UT campus, West Campus, North University, Hyde Park edges, medical/institutional areas, and downtown-facing corridors, increasing variability in offense patterns.

(PCII) PROPERTY CRIME

(PCII) Precise 2-mile count unavailable. Property crime exposure likely increases with broader inclusion of retail, parking, student housing, and institutional nodes.

(PCII) BURGLARY

(PCII) No validated 2-mile burglary count available. Review APD NIBRS burglary/breaking and entering records once center coordinates are validated.

(PCII) ROBBERY

(PCII) No validated 2-mile robbery count available. Risk is concentrated around late-night pedestrian routes, cash/retail nodes, transit stops, and parking areas.

(PCII) MOTOR VEHICLE THEFT

(PCII) No validated 2-mile motor vehicle theft count available. Central Austin parking concentration increases exposure.

(PCII) THEFT

(PCII) No validated 2-mile theft count available. Larceny/theft remains the likely dominant property-crime category based on APD citywide patterns.

(PCII) VANDALISM

(PCII) No validated 2-mile vandalism count available. Review destruction/damage/vandalism of property records in APD NIBRS.

(PCII) DRUG ACTIVITY

(PCII) No validated 2-mile drug activity count available. Review APD Crimes Against Society and non-indexed categories.

(PCII) OTHER

(PCII) No validated 2-mile counts for homicide, weapons, arson, fraud, shoplifting, sex crimes, trespass, disorderly conduct, gang activity, package theft, catalytic converter theft, or commercial burglary were obtained.

3 MILE RADIUS**(PCII) VIOLENT CRIME**

(PCII) Precise 3-mile count unavailable. The 3-mile radius would likely include portions of downtown, UT, Hyde Park, central corridors, and major commercial/entertainment areas, which could elevate robbery, aggravated assault, disorder, and weapons exposure relative to a purely residential area.

(PCII) PROPERTY CRIME

(PCII) Precise 3-mile count unavailable. The 3-mile area likely contains high-density housing, retail, entertainment, medical, institutional, and parking assets; property-crime exposure is expected to be elevated.

(PCII) BURGLARY

(PCII) No validated 3-mile burglary count available. Commercial and residential burglary should be queried from APD NIBRS with confirmed coordinates.

(PCII) ROBBERY

(PCII) No validated 3-mile robbery count available. Risk is assessed as moderate due to urban density and late-night activity zones.

(PCII) MOTOR VEHICLE THEFT

(PCII) No validated 3-mile motor vehicle theft count available. Review APD NIBRS motor vehicle theft and local parking-crime reports.

(PCII) THEFT

(PCII) No validated 3-mile theft count available. Theft remains the primary expected exposure.

(PCII) VANDALISM

(PCII) No validated 3-mile vandalism count available. Vandalism/criminal mischief risk is moderate.

(PCII) DRUG ACTIVITY

(PCII) No validated 3-mile drug activity count available. Drug/narcotic violations require APD NIBRS extraction.

(PCII) OTHER

(PCII) No validated 3-mile counts for homicide, weapons, arson, fraud, shoplifting, sex crimes, trespass, disorderly conduct, gang activity, package theft, catalytic converter theft, or commercial burglary were obtained.

(PCII) VS NATIONAL

(PCII) No radius-specific rate was calculated. Nationally, BJS/FBI reported the U.S. violent offense rate decreased from 393.9 per 100,000 in 2023 to 370.8 per 100,000 in 2024. This benchmark is not directly comparable to an unverified 78705 radius without local counts and denominator. ([bjs.ojp.gov\(https://bjs.ojp.gov/library/publications/crime-known-law-enforcement-2024?utm_source=openai\)](https://bjs.ojp.gov/library/publications/crime-known-law-enforcement-2024?utm_source=openai))

(PCII) VS STATE

(PCII) Texas 2024 violent and property crime rates were reported by USAFacts as higher than the U.S. average, using FBI data; Texas DPS reported 2024 violent crime volume decreased 2.7% and property crime volume decreased 6.9% from 2023 to 2024. These are state-level benchmarks only. ([usafacts.org\(https://usafacts.org/answers/what-is-the-crime-rate-in-the-us/state/texas/?utm_source=openai\)](https://usafacts.org/answers/what-is-the-crime-rate-in-the-us/state/texas/?utm_source=openai))

(PCII) VS COUNTY

(PCII) No Travis County comparison rate was validated for the precise radius in this assessment. County comparison should be derived from FBI CDE or TXDPS county-level datasets and normalized per 100,000 population.

(PCII) VS CITY

(PCII) Austin citywide and district-level indicators show property/society offenses as a dominant issue. In APD materials, January-May 2025 citywide larceny/theft offenses were 8,743; burglary/breaking and entering 1,538; motor vehicle theft 1,826; destruction/damage/vandalism 2,440; and drug/narcotic offenses 2,851. (bandc.crccheck.com(https://bandc.crccheck.com/public-safety-commission/454220-item-3-apd-quarterly-update-data-and-backup-materials/?utm_source=openai))

(PCII) FIVE YEAR TREND

(PCII) Address-specific 5-year trend unavailable. APD quarterly materials compare 2025 categories against 5-year means for citywide offenses; for January-May 2025, burglary, larceny/theft, motor vehicle theft, and vandalism were below their 5-year means, while drug/narcotic offenses and weapons law violations were above their 5-year means. (bandc.crccheck.com(https://bandc.crccheck.com/public-safety-commission/454220-item-3-apd-quarterly-update-data-and-backup-materials/?utm_source=openai))

(PCII) YEAR OVER YEAR

(PCII) For Austin Council District 9, APD quarterly materials show property/society offenses decreased from 4,095 in January-May 2024 to 3,746 in January-May 2025, a 9% decrease; persons offenses increased from 1,134 to 1,220, an 8% increase. (services.austintexas.gov(https://services.austintexas.gov/edims/document.cfm?id=454220&utm_source=openai))

(PCII) SEASONAL

(PCII) No address-specific seasonal trend was extracted. University-district risk should be expected to fluctuate with academic calendar, move-in/move-out, football/events, holidays, summer occupancy drops, and late-night entertainment cycles.

(PCII) TIME OF DAY

(PCII) No address-specific time-of-day trend was extracted. Expected higher theft/vehicle/trespass risk during evening, overnight, bar close, low-staffing periods, and delivery/package dwell times.

(PCII) DAY OF WEEK

(PCII) No address-specific day-of-week trend was extracted. Expected elevated disorder, intoxication-related incidents, and pedestrian conflict Thursday-Saturday nights and during major UT/downtown events.

C**CRIME DENSITY OBSERVATIONS**

- (PCII) Crime density cannot be quantified without validated geocoding and APD record extraction.
- (PCII) Qualitatively, the 78705/UT-area setting is likely to show density along Guadalupe Street/The Drag, West Campus apartment corridors, transit nodes, parking structures/lots, convenience retail, entertainment/restaurant clusters, and campus-adjacent pedestrian routes.

D**DATA CONFIDENCE**

(PCII) Medium for citywide, district, and ZIP-level context; Low for address-specific and 1-/2-/3-mile crime counts because the exact address and public radius extraction were not verified.

Demographic Analysis

(PCII) POPULATION

(PCII) ZIP 78705 population: 33,238 based on ACS 2024 5-year data. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) POPULATION DENSITY

(PCII) 16,056.8 people per square mile across 2.1 square miles, indicating very high urban density. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) MEDIAN HOUSEHOLD INCOME

(PCII) \$32,380 plus/minus \$5,671; this is low relative to the Austin metro, Texas, and U.S. benchmarks and likely reflects student-heavy household composition. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) AVERAGE HOUSEHOLD SIZE

(PCII) 1.8 persons per household; 12,136 households were reported. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) EMPLOYMENT

(PCII) Employment rate was not captured from the reviewed Census Reporter profile lines. Because the ZIP is student-heavy, standard employment metrics should be interpreted cautiously and verified through ACS table-level data before use in underwriting.

(PCII) VACANCY RATE

(PCII) Estimated vacancy from available Census Reporter figures: 13,619 housing units minus 12,136 households suggests approximately 1,483 non-household/vacant units, or roughly 10.9%; this is an inference from reported units and households, not a directly cited vacancy statistic. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) OWNER OCCUPANCY

(PCII) Owner/renter split not available from reviewed profile lines. Given the West Campus/North University context and apartment-heavy character, renter occupancy is expected to be high, but exact rate was not verified.

(PCII) RENTAL OCCUPANCY

(PCII) Exact rental occupancy rate not verified from reviewed sources; high rental turnover is strongly suggested by 52.2% of residents having moved since the prior year. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

(PCII) COMMERCIAL ACTIVITY

(PCII) Commercial activity is moderate to high, driven by UT campus proximity, apartments, student services, restaurants, convenience retail, transit access, and nearby medical/institutional uses. UT off-campus resources describe West Campus and North University as having shops, grocery access, parks, and bus stops nearby. (offcampus.utexas.edu(https://offcampus.utexas.edu/neighborhoods?utm_source=openai))

(PCII) GROWTH TRENDS

(PCII) Annual mobility is very high: 52.2% of ZIP residents moved since the previous year, more than double the Austin metro, Texas, and U.S. rates. This indicates high turnover and increased challenges for access control, tenant awareness, package security, and community guardianship. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

POPULATION

(PCII) ZIP 78705 population: 33,238 based on ACS 2024 5-year data.
(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

POPULATION DENSITY

(PCII) 16,056.8 people per square mile across 2.1 square miles, indicating very high urban density.
(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

MEDIAN HOUSEHOLD INCOME

(PCII) \$32,380 plus/minus \$5,671; this is low relative to the Austin metro, Texas, and U.S. benchmarks and likely reflects student-heavy household composition.
(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

AVERAGE HOUSEHOLD SIZE

(PCII) 1.8 persons per household; 12,136 households were reported.
(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

EMPLOYMENT

(PCII) Employment rate was not captured from the reviewed Census Reporter profile lines. Because the ZIP is student-heavy, standard employment metrics should be interpreted cautiously and verified through ACS table-level data before use in underwriting.

VACANCY RATE

(PCII) Estimated vacancy from available Census Reporter figures: 13,619 housing units minus 12,136 households suggests approximately 1,483 non-household/vacant units, or roughly 10.9%; this is an inference from reported units and households, not a directly cited vacancy statistic.

VACANCY RATE (CONT.)

(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

OWNER OCCUPANCY

(PCII) Owner/renter split not available from reviewed profile lines. Given the West Campus/North University context and apartment-heavy character, renter occupancy is expected to be high, but exact rate was not verified.

RENTAL OCCUPANCY

(PCII) Exact rental occupancy rate not verified from reviewed sources; high rental turnover is strongly suggested by 52.2% of residents having moved since the prior year.
(censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))

COMMERCIAL ACTIVITY

(PCII) Commercial activity is moderate to high, driven by UT campus proximity, apartments, student services, restaurants, convenience retail, transit access, and nearby medical/institutional uses. UT off-campus resources describe West Campus and North University as having shops, grocery access, parks, and bus stops nearby.
(offcampus.utexas.edu(https://offcampus.utexas.edu/neighborhoods?utm_source=openai))

GROWTH TRENDS

(PCI) Annual mobility is very high: 52.2% of ZIP residents moved since the previous year, more than double the Austin metro, Texas, and U.S. rates. This indicates high turnover and increased challenges for access control, tenant awareness, package security, and community guardianship.

GROWTH TRENDS (CONT.)

([censusreporter.org](https://censusreporter.org/profiles/86000US78705-78705/)(<https://censusreporter.org/profiles/86000US78705-78705/>))

Environmental Risk Analysis

FLOOD RISK

(PCII) ANALYSIS

(PCII) Parcel-level floodplain status was not verified. Austin directs users to FloodPro to determine whether a property is in a floodplain and to access FEMA map-change information, storm-drain infrastructure, and floodplain models. Travis County states Central Texas, including Travis County, is known as Flash Flood Alley. (austintexas.gov(https://www.austintexas.gov/services/view-floodplain-maps-and-storm-drain-infrastructure?utm_source=openai))

WILDFIRE RISK

(PCII) ANALYSIS

(PCII) Central urban 78705 wildfire exposure is likely lower than wildland-urban interface areas of west Travis County, but county/regional wildfire planning is material. Austin/Travis County maintains a Community Wildfire Protection Plan, and Travis County wildfire resources state Central Texas is second only to California for wildfire risk. (austintexas.gov(https://www.austintexas.gov/emergency-management/austintravis-county-community-wild-fire-protection-plan?utm_source=openai))

EARTHQUAKE EXPOSURE

(PCII) ANALYSIS

(PCII) Earthquake exposure is not a dominant central Austin hazard; county-level FEMA NRI derivative data cited earthquake risk at 53.5 for Travis County, materially lower than tornado, flood, and wildfire risk scores in that source. This is county-level only. (riskbycounty.com(https://riskbycounty.com/texas/travis-county?utm_source=openai))

SEVERE WEATHER

(PCII) ANALYSIS

(PCII) Severe weather risk is material: county-level FEMA NRI derivative data identifies high exposure to tornado, flood, wildfire, hurricane, and other hazards; separate disaster-risk summaries identify tornado, hail, and heat wave as major drivers of expected annual losses. (riskbycounty.com(https://riskbycounty.com/texas/travis-county?utm_source=openai))

INDUSTRIAL HAZARDS

(PCII) ANALYSIS

(PCII) No parcel-specific industrial hazard or nearby hazardous industrial site was verified. Central Austin exposure is more likely from transportation corridors, building mechanical systems, fuel stations, laboratories/institutional facilities, construction activity, and utility infrastructure than heavy industry.

HAZARDOUS MATERIALS

(PCII) ANALYSIS (PCII) No specific hazardous-materials site was verified within a defined radius. Recommended follow-up: query EPA ECHO, TCEQ, Austin GIS, fire pre-plans, nearby laboratories, fuel stations, dry cleaners, and generator/storage permits once coordinates are confirmed.

NEARBY RISK FACTORS

(PCII) ANALYSIS

(PCII) Factor: University of Texas campus and student-housing concentration | Distance: Approximate neighborhood context; exact distance not verified | Risk Impact: Increases pedestrian density, transient occupancy, late-night movement, event surges, package theft, bicycle/scooter theft, and access-control complexity; also improves natural surveillance and access to UTPD resources.; Factor: West Campus/North University dense apartments and multitenant buildings | Distance: Neighborhood-level context | Risk Impact: Increases anonymity, tailgating risk, shared-entry vulnerabilities, package/mail theft, parking exposure, and nuisance activity; supports passive surveillance during active hours.; Factor: Restaurants, bars, convenience retail, and campus-serving commercial uses | Distance: Neighborhood-level context | Risk Impact: Increases after-hours foot traffic, intoxication/disorder risk, robbery exposure, and theft opportunities near entrances and parking.; Factor: Transit stops and UT/CapMetro routes | Distance: Neighborhood-level context | Risk Impact: Improves accessibility for staff/customers and emergency mobility, but increases pedestrian permeability and potential for loitering near stops. CapMetro route resources identify West Campus/UT route service and Rapid service through UT/downtown corridors. ([app.capmetro.org\(https://app.capmetro.org/AspSingleForms/SingleForm/turnbyturndescription?data=642&utmsource=openai\)](https://app.capmetro.org/AspSingleForms/SingleForm/turnbyturndescription?data=642&utmsource=openai)); Factor: Schools and youth-serving/institutional facilities | Distance: Within broader 78705/Hyde Park/UT context | Risk Impact: Increases life-safety planning requirements, traffic/pedestrian congestion, and sensitivity to suspicious activity; nearby schools also increase daytime guardianship. Hyde Park-area school resources identify Lee Elementary, Ridgetop Elementary, Kealing, Lamar, and McCallum serving the broader area; St. Austin Catholic School is in Austin 78705. ([austinhdepark.org\(https://www.austinhdepark.org/schools?utmsource=openai\)](https://www.austinhdepark.org/schools?utmsource=openai)); Factor: Hospitals/medical facilities | Distance: St. David's Medical Center is in ZIP 78705 at 919 E. 32nd Street | Risk Impact: Improves emergency medical access; also introduces traffic, ambulance activity, vulnerable populations, and potential behavioral-health spillover risk near medical corridors. ([stdavids.com\(https://www.stdavids.com/locations/st-davids-medical-center/about-us/contact-us?utmsource=openai\)](https://www.stdavids.com/locations/st-davids-medical-center/about-us/contact-us?utmsource=openai)); Factor: Fire station proximity | Distance: Austin Fire Station 3 is at 201 W. 30th Street in ZIP 78705 | Risk Impact: Reduces fire/EMS response-time risk at the neighborhood level, but does not substitute for code-compliant fire alarm, sprinkler, egress, and staff evacuation procedures. ([austintexas.gov\(https://www.austintexas.gov/fire/index-austin-fire-facilities\)](https://www.austintexas.gov/fire/index-austin-fire-facilities)); Factor: Flash-flood alley regional context | Distance: County/regional hazard context | Risk Impact: Increases need for parcel-level floodplain review, storm-drain evaluation, water-intrusion planning, tenant notification, and business continuity procedures. ([traviscountytexas.gov\(https://www.traviscountytexas.gov/emergency/preparedness?utmsource=openai\)](https://www.traviscountytexas.gov/emergency/preparedness?utmsource=openai)); Factor: Vacant buildings, abandoned structures, homeless encampments, pawn shops, cannabis retailers, banks/ATMs, hotels/motels, industrial areas, storage facilities, rail lines, power substations, telecom facilities, airports, ports, government buildings, correctional facilities, and hazardous-materials facilities | Distance: Not verified within 1-, 2-, or 3-mile radius | Risk Impact: These factors require GIS/field verification. If present nearby, they may affect loitering, theft, robbery, concealment, emergency response, protest/civil unrest, utility continuity, or hazardous exposure risk.

ENVIRONMENTAL SUMMARY

(PCI) ANALYSIS

(PCI) Environmental risk is moderate: natural hazards are dominated by flood/flash-flood, hail, extreme heat, severe thunderstorm, tornado, drought, and some wildfire exposure at the regional/county level; security environment is dominated by dense urban/student activity, pedestrian permeability, and multitenant access-control challenges.

CPTED Assessment

S

NATURAL SURVEILLANCE

0.6/10

CRITICAL

(PCII) SCORE (PCII) 0.6/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

ACCESS CONTROL

0.5/10

CRITICAL

(PCII) SCORE (PCII) 0.5/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

TERRITORIAL REINFORCEMENT

0.5/10

CRITICAL

(PCII) SCORE (PCII) 0.5/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

MAINTENANCE

0.5/10

CRITICAL

(PCII) SCORE (PCII) 0.5/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

LIGHTING

0.5/10

CRITICAL

(PCII) SCORE (PCII) 0.5/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

WAYFINDING

0.6/10

CRITICAL

(PCII) SCORE (PCII) 0.6/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

DEFENSIBLE SPACE

0.5/10

CRITICAL

(PCII) SCORE (PCII) 0.5/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

S

ACTIVITY SUPPORT

0.6/10

CRITICAL

(PCII) SCORE (PCII) 0.6/10
(PCII) RISK (PCII) Critical
(PCII) RECOMMENDATION (PCII) Not Provided
(PCII) FINDINGS (PCII) Not Provided

Threat Matrix

Threat	Likelihood	Impact	Risk	Priority	Mitigation
Theft/larceny of business property, personal property, packages, bicycles, scooters, or electronics	5	3	High	Immediate	Install visible cameras, secure package/mail area, lockable storage, asset inventory, staff awareness, signage, and rapid reporting procedures.
Vehicle burglary, motor vehicle theft, and catalytic converter theft	4	3	High	Immediate	Improve parking lighting, camera coverage, patrol/guardianship, license-plate capture where lawful, signage, catalytic-converter protection guidance, and removal of valuables from vehicles.
Unauthorized access/tailgating into suite, lobby, corridor, elevator, stairwell, or service area	4	4	High	Immediate	Deploy access control, door position monitoring, anti-tailgating awareness, visitor/vendor procedures, badge policy, key control, and audit logs.
Burglary or after-hours forced entry	3	4	High	Immediate	Harden doors/windows, alarm all perimeter openings, monitor intrusion signals, improve lighting, verify camera coverage, and secure high-value assets out of view.
Trespass, loitering, disorderly conduct, public intoxication, or nuisance activity	4	3	High	Immediate	Establish trespass authorization with APD where applicable, use lighting/signage, remove concealment, implement staff escalation protocols, and coordinate with landlord/property management.
Robbery or assault affecting staff, customers, or visitors	3	5	High	High	Use cashless/low-cash procedures, duress alarms, camera coverage, safe opening/closing procedures, buddy system after hours, and employee security training.
Vandalism, graffiti, and criminal mischief	4	2	Medium	Medium	Rapid removal, lighting, cameras, anti-graffiti coatings, controlled access to service areas, and reporting of repeat incidents.

Threat Matrix (Cont.)

Threat	Likelihood	Impact	Risk	Priority	Mitigation
Severe weather, flash flooding, hail, extreme heat, or power outage	4	4	High	High	Verify floodplain and drainage status, create severe-weather procedures, maintain emergency supplies, UPS/backups for security systems, communications plan, and insurance review.
Fire/life-safety incident	2	5	High	High	Verify fire alarm, sprinkler, extinguishers, egress lighting, exit signage, evacuation routes, drills, occupancy load, and fire department pre-plan coordination.
Civil unrest, protest spillover, or major-event crowd disruption	2	4	Medium	Medium	Monitor UT/downtown event schedules, create closure/lockdown criteria, secure storefront/entries, and coordinate with landlord and law enforcement.

Business Impact Analysis

P**PEOPLE**

- (PCII) Primary people risks include robbery/assault, unauthorized entry, intoxication/disorder encounters, severe weather, fire, and medical emergencies.
- (PCII) Controls should prioritize staff training, duress communication, evacuation/shelter procedures, and safe opening/closing protocols.

O**OPERATIONS**

- (PCII) Operational disruption could result from burglary investigation, access-system failure, power outage, severe weather, water intrusion, police activity, building closure, or staffing shortages during campus events.

P**PROPERTY**

- (PCII) Most likely losses involve theft of portable assets, package theft, vehicle-related theft, vandalism, door/window damage, and water/storm damage.
- (PCII) Loss severity increases if high-value equipment or sensitive records are stored onsite.

R**REVENUE**

- (PCII) Revenue exposure depends on the undefined business type 600.
- (PCII) Likely impacts include downtime, customer access interruption, repair costs, lost inventory/equipment, and increased security/insurance costs.

C**COMPLIANCE**

- (PCII) Applicable requirements may include OSHA emergency action planning, fire code, ADA access, data/privacy obligations for cameras and access logs, lease security obligations, and industry-specific requirements that could not be determined from business type code 600.

R**REPUTATION**

- (PCII) Repeated theft, disorder, unauthorized access, or safety incidents can reduce customer confidence, employee retention, landlord confidence, and insurer perception.

I

INSURANCE EXPOSURE

- (PCII) Insurance exposure is moderate-to-high due to theft, vandalism, vehicle-related claims, storm/hail/flood risk, and unverified protective safeguards.
- (PCII) Verify property, general liability, business interruption, crime, cyber, equipment, flood, and wind/hail coverage.

S

SUPPLY CHAIN

- (PCII) If the facility relies on scheduled deliveries, curbside loading, or shared mailrooms, package theft and delivery disruption are material.
- (PCII) Vendor access control and delivery verification should be implemented.

R

RECOVERY TIME

- (PCII) Without a documented business continuity plan, recovery time could range from same day for minor theft to multiple days/weeks for burglary damage, water intrusion, power outage, or system loss.
- (PCII) Establish recovery time objectives by function.

Nearby Infrastructure

S SCHOOLS

- (PCII) University of Texas at Austin campus facilities in broader neighborhood context
- (PCII) St. Austin Catholic School, Austin, TX 78705; exact distance from submitted address not verified. (staustinschool.org(https://www.staustinschool.org/?utm_source=openai))
- (PCII) Lee Elementary School serving the Hyde Park area; exact distance not verified. (austinhdepark.org(https://www.austinhdepark.org/schools?utm_source=openai))
- (PCII) Ridgetop Elementary School serving the Hyde Park area; exact distance not verified. (austinhdepark.org(https://www.austinhdepark.org/schools?utm_source=openai))
- (PCII) Kealing Middle School serving the broader area; exact distance not verified. (austinhdepark.org(https://www.austinhdepark.org/schools?utm_source=openai))

H HOSPITALS

- (PCII) St. David's Medical Center, 919 E. 32nd St, Austin, TX 78705. (stdavids.com(https://www.stdavids.com/locations/st-davids-medical-center/about-us/contact-us?utm_source=openai))
- (PCII) Dell Seton Medical Center at The University of Texas; nearby central Austin medical/institutional resource, exact distance not verified in reviewed sources

P POLICE STATIONS

- (PCII) University of Texas Police Department main building, 2201 Robert Dedman Dr, Austin, TX 78712. (police.utexas.edu(https://police.utexas.edu/contact/map?utm_source=openai))
- (PCII) UTPD West satellite office, 2400 Nueces Street. (police.utexas.edu(https://police.utexas.edu/contact/map?utm_source=openai))
- (PCII) Austin Police Department headquarters, 715 East 8th St. (austintexas.gov(<https://www.austintexas.gov/police/contact>))

F FIRE STATIONS

- (PCII) Austin Fire Station 3, 201 W. 30th St, ZIP 78705. (austintexas.gov(<https://www.austintexas.gov/fire/index-austin-fire-facilities>))
- (PCII) Austin Fire Station 2, 506 W. Martin Luther King Jr. Blvd, ZIP 78701. (austintexas.gov(<https://www.austintexas.gov/fire/index-austin-fire-facilities>))

G GOVERNMENT BUILDINGS

- (PCII) University of Texas public institution facilities nearby
- (PCII) Texas Capitol complex in central Austin; exact distance not verified in this assessment
- (PCII) Austin Police Department headquarters, 715 East 8th St. (austintexas.gov(<https://www.austintexas.gov/police/contact>))

C**CRITICAL INFRASTRUCTURE**

- (PCII) Austin Fire Station 3 public safety facility
- (PCII) UTPD and APD law enforcement facilities
- (PCII) St. David's Medical Center
- (PCII) CapMetro/UT transit routes and bus stops
- (PCII) Austin Energy and telecom distribution infrastructure presumed in urban grid; specific substations/telecom nodes not verified

T**TRANSPORTATION ROUTES**

- (PCII) Guadalupe Street/The Drag corridor
- (PCII) Lamar Boulevard
- (PCII) Martin Luther King Jr. Boulevard
- (PCII) Dean Keeton Street
- (PCII) I-35 east of UT/downtown context
- (PCII) Local West Campus/North University street grid

T**TRANSIT STATIONS**

- (PCII) CapMetro West Campus/UT route service, including Route 642 West Campus/UT loop. (app.capmetro.org(http://app.capmetro.org/AspSingleForms/SingleForm/turnbyturndescription?data=642&utm_source=openai))
- (PCII) CapMetro Rapid corridors serving UT/downtown; Rapid service is described as frequent, with routes including 803 Burnet/South Lamar through UT/downtown contexts. (capmetro.org(https://www.capmetro.org/rapid?utm_source=openai))
- (PCII) UT shuttle routes serving West Campus and campus areas. (parking.utexas.edu(https://parking.utexas.edu/transportation/shuttle/shuttle-route-map-detail?utm_source=openai))

R**RAIL LINES**

- (PCII) No rail line was verified within the immediate address context from reviewed sources; broader central Austin rail infrastructure should be checked in GIS if needed.

P**POWER SUBSTATIONS**

- (PCII) No specific nearby power substation was verified from reviewed sources; Austin Energy/GIS verification recommended.

S

STORAGE FACILITIES

- (PCII) No specific storage facility was verified within a defined radius from reviewed sources; field/GIS validation recommended.

Sources

SITE REPORT SOURCES

- [1] (PCII) City of Austin, View Crime Statistics / APD CrimeViewer, accessed July 2026: <https://www.austintexas.gov/services/view-crime-statistics>
- [2] (PCII) City of Austin Open Data / APD NIBRS Group A Offense Crimes dataset via Data.gov, dataset last updated June 15, 2026; catalog checked June 28, 2026: <https://catalog.data.gov/dataset/nibrs-group-a-offense-crimes>
- [3] (PCII) Census Reporter, ZIP 78705 profile, ACS 2024 5-year data, accessed July 2026: <https://censusreporter.org/profiles/86000US78705-78705/>
- [4] (PCII) UnitedStatesZipCodes.org, ZIP Code 78705 demographics and coordinates, accessed July 2026: <https://www.unitedstateszipcodes.org/78705/>
- [5] (PCII) City of Austin, FloodPro / View floodplain maps and storm drain infrastructure, accessed July 2026: <https://www.austintexas.gov/services/view-floodplain-maps-and-storm-drain-infrastructure>
- [6] (PCII) City of Austin Open Data, Greater Austin Fully Developed Floodplain, accessed July 2026: <https://data.austintexas.gov/Public-Safety/Greater-Austin-Fully-Developed-Floodplain/2xn4-j3u2>
- [7] (PCII) Travis County, Floodplain Maps, accessed July 2026: <https://www.traviscountytexas.gov/tnr/environmental-quality/stormwater/floodplain>
- [8] (PCII) Travis County, Emergency Preparedness, accessed July 2026: <https://www.traviscountytexas.gov/emergency/preparedness>
- [9] (PCII) Texas Commission on Environmental Quality, Central Registry, accessed July 2026: https://www.tceq.texas.gov/permitting/central_registry
- [10] (PCII) Texas Commission on Environmental Quality, Industrial and Hazardous Waste Queries and Notices of Registration, accessed July 2026: https://www.tceq.texas.gov/permitting/registration/iHW/iHW_query.html
- [11] (PCII) City of Austin, Index of Austin Fire Facilities, accessed July 2026: <https://www.austintexas.gov/fire/index-austin-fire-facilities>
- [12] (PCII) Austin Police Department Contact page, accessed July 2026: <https://www.austintexas.gov/police/contact>
- [13] (PCII) University of Texas at Austin, Safety and Security Resources, accessed July 2026: <https://www.utexas.edu/campus-life/safety-and-security>
- [14] (PCII) University of Texas Police Department, About UTPD, accessed July 2026: <https://police.utexas.edu/about>
- [15] (PCII) Texas Health and Human Services / hospital payment file reference identifying St. David's and Dell Seton facilities, accessed July 2026: <https://pfd.hhs.texas.gov/sites/default/files/documents/hospital-svcs/2025/2025-fy-hosp-urban-sda.pdf>
- [16] (PCII) FEMA National Risk Index Technical Documentation v1.20, December 2025 / published 2026, accessed July 2026: <https://www.fema.gov/sites/default/files/documents/femanational-risk-indextechnical-documentation.pdf>

SITE INTELLIGENCE SOURCES

- [17] (PCII) Census Reporter, ZIP Code 78705 ACS 2024 5-year profile, accessed July 21, 2026. (censusreporter.org(<https://censusreporter.org/profiles/86000US78705-78705/>))
- [18] (PCII) City of Austin / Data.gov, NIBRS Group A Offense Crimes dataset metadata, dataset last updated June 15, 2026, catalog checked June 28, 2026. (catalog.data.gov(<https://catalog.data.gov/dataset/nibrs-group-a-offense-crimes>))
- [19] (PCII) City of Austin, View Crime Statistics / CrimeViewer description and data limitations, accessed July 21, 2026. (austintexas.gov(<https://www.austintexas.gov/services/view-crime-statistics>))
- [20] (PCII) Austin Public Safety Commission backup / APD Quarterly Update, January-May 2025 crime tables, accessed July 21, 2026. (bandc.crccheck.com(https://bandc.crccheck.com/public-safety-commission/454220-item-3-apd-quarterly-update-data-and-backup-materials/?utm_source=openai))
- [21] (PCII) Austin Fire Department, Index of Austin Fire Facilities, accessed July 21, 2026. (austintexas.gov(<https://www.austintexas.gov/fire/index-austin-fire-facilities>))
- [22] (PCII) University of Texas Police Department contact/map pages, accessed July 21, 2026. (police.utexas.edu(https://police.utexas.edu/contact?utm_source=openai))
- [23] (PCII) Austin Police Department contact page, accessed July 21, 2026. (austintexas.gov(<https://www.austintexas.gov/police/contact>))

- [24] (PCII) St. David's Medical Center contact page, accessed July 21, 2026. (stdavids.com(https://www.stdavids.com/locations/st-davids-medical-center/about-us/contact-us?utm_source=openai))
- [25] (PCII) City of Austin FloodPro / floodplain maps and storm drain infrastructure service page, accessed July 21, 2026. (austintexas.gov(https://www.austintexas.gov/services/view-floodplain-maps-and-storm-drain-infrastructure?utm_source=openai)))
- [26] (PCII) Travis County Emergency Preparedness page, accessed July 21, 2026. (traviscountytexas.gov(https://www.traviscountytexas.gov/emergency/preparedness?utm_source=openai))
- [27] (PCII) Austin/Travis County Community Wildfire Protection Plan page, accessed July 21, 2026. (austintexas.gov(https://www.austintexas.gov/emergency-management/austintravis-county-community-wildfire-protection-plan?utm_source=openai))
- [28] (PCII) Travis County wildfire information resources, accessed July 21, 2026. (traviscountytexas.gov(https://www.traviscountytexas.gov/investment-management/2704-wildfire-information?utm_source=openai))
- [29] (PCII) FEMA National Risk Index derivative county summary for Travis County, RiskByCounty, FEMA NRI v1.20 December 2025 cited by source, accessed July 21, 2026. (riskbycounty.com(https://riskbycounty.com/texas/travis-county?utm_source=openai))
- [30] (PCII) Bureau of Justice Statistics, Crime Known to Law Enforcement, 2024, accessed July 21, 2026. (bjs.ojp.gov(https://bjs.ojp.gov/library/publications/crime-known-law-enforcement-2024?utm_source=openai))
- [31] (PCII) Texas Department of Public Safety, 2024 Crime in Texas Annual Report, accessed July 21, 2026. (dps.texas.gov(https://www.dps.texas.gov/crimereports/24/2024cit.pdf?utm_source=openai))
- [32] (PCII) CapMetro schedules/maps, West Campus/UT route, and Rapid service pages, accessed July 21, 2026. (capmetro.org(https://www.capmetro.org/ride/plan/schedmap?utm_source=openai))
- [33] (PCII) UT Austin Off-Campus Living Resources neighborhood descriptions, accessed July 21, 2026. (offcampus.utexas.edu(https://offcampus.utexas.edu/neighborhoods?utm_source=openai))
- [34] (PCII) Hyde Park Neighborhood Association area public schools and St. Austin Catholic School pages, accessed July 21, 2026. (austinhypark.org(https://www.austinhypark.org/schools?utm_source=openai))



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
AREA NAME	Perimeter
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

60 / 100

RISK CLASSIFICATION

MEDIUM RISK

EXECUTIVE DASHBOARD

SECURITY SCORE 60 / 100	RISK CLASSIFICATION MEDIUM RISK
ASSESSED MEDIA 2 Media	SECURITY DEVICES 0 Installed
FIELD DICTATIONS 1 Recorded	CPTED EVALUATED YES

1. Executive Summary

Assessment Summary

- (PCII) The overall security posture of the Clayton Jerde facility perimeter is moderately effective but requires enhancements to meet a higher security standard. Key strengths include the presence of a security guard, a manual boom barrier controlling vehicle entry, and a well-maintained perimeter fence. However, critical vulnerabilities exist, such as a partially obstructed CCTV camera, lack of electronic access control systems, and an open entrance gate during operational hours. These gaps expose the facility to unauthorized access and reduce its deterrent capability. The lack of a visitor management kiosk further complicates the tracking and verification of visitors, increasing liability risks. The CPTED assessment highlights deficiencies in natural surveillance and access control, while maintenance and territorial reinforcement are relatively stronger. To improve security maturity, strategic recommendations include installing electronic access control systems, repositioning the CCTV camera, and implementing a visitor management system. Post-remediation, the facility is expected to achieve a more robust security posture, significantly reducing the risk of unauthorized access and enhancing operational security.

2. Facility Overview & Scope

(PCII) Facility Structure & Context:

(PCII) The Clayton Jerde facility is located at 742 Maple Ridge Lane, Austin, TX. The perimeter is defined by a well-maintained fence, with a main entrance featuring a security guard post and a manual boom barrier for vehicle control. Signage instructs visitors to check in at the office, and the landscape is complemented by trees and shrubs, providing a clean and orderly environment. However, these natural elements partially obstruct surveillance equipment, impacting visibility. The entrance gate remains open during business hours, which is a critical point of vulnerability.

(PCII) Assessment Boundaries & Scope:

(PCII) The assessment focused on evaluating the physical security measures at the Clayton Jerde facility's perimeter. Analysis was based on visual evidence, dictation notes, and CPTED principles. Limitations include the absence of detailed device deployment data and the inability to assess internal facility security controls. Recommendations are drawn from observable conditions and potential threat vectors.

3. Evidence Summary

(PCII) The primary evidence for this assessment is a high-resolution image of the facility's main entrance, supplemented by detailed dictation notes. Observations include the presence of a security guard, a manual boom barrier, signage, and a CCTV camera with a partially obstructed view. The perimeter fence is in good condition, but the lack of electronic access control and visitor management systems are notable weaknesses. The image provides a comprehensive view of the entrance layout, supporting the identification of key vulnerabilities and strengths.

4. Existing Controls

(PCII) Existing controls at the facility include a security guard at the entrance, a manual boom barrier for vehicles, and a perimeter fence. A CCTV camera is installed but partially obstructed by a tree. These controls provide basic deterrence but lack the sophistication of electronic access systems. The manual nature of the boom barrier and the absence of automated visitor management limit the effectiveness of access control.

5. Device Analysis

(PCII) The CCTV camera near the entrance is strategically placed but suffers from partial obstruction due to foliage, limiting its field of view. No other electronic security devices are visible, such as card readers or biometric systems, which could enhance access control. The manual boom barrier is functional but does not provide the same level of security as automated systems.

6. Dictation Analysis

(PCII) The dictation notes corroborate the visual evidence, highlighting the presence of a security guard, a manual boom barrier, and a partially obstructed CCTV camera. The absence of electronic access controls and visitor management systems is a critical vulnerability. The open gate during operational hours is a significant risk factor, as it allows for uncontrolled access.

7. CPTED Analysis

(PCII) The CPTED assessment reveals that while territorial reinforcement and maintenance are strong, natural surveillance and access control are lacking. The positioning of trees and shrubs creates blind spots for surveillance cameras. The open gate during business hours undermines access control efforts. Recommendations include repositioning the CCTV camera and enhancing natural surveillance by trimming foliage.

8. Threat Scenarios

(PCII) Threat scenarios include unauthorized individuals entering the facility through the open gate, social engineering attacks facilitated by the lack of visitor management, and potential vandalism due to limited surveillance coverage.

9. Business Impact

Business Impact

Summary:

Security gaps at the entrance could lead to unauthorized access, resulting in potential theft, vandalism, or safety risks to personnel. The lack of visitor management increases liability and complicates emergency response efforts. Operational disruptions could occur if security breaches are not promptly addressed.

10. Remediation Plan

Remediation Plan

Summary:

The remediation plan prioritizes immediate repositioning of the CCTV camera and installation of electronic access controls. Short-term actions include automating the boom barrier and enhancing perimeter security. Long-term strategies involve regular security reviews and technology upgrades to maintain a high security standard.

11. Residual Risk

Residual Risk

Summary:

After implementing the recommended improvements, residual risks will primarily involve ongoing maintenance of electronic systems and vigilance against new threat vectors. Regular audits and upgrades will be necessary to sustain security effectiveness.

12. CPTED Security Snapshot

(PCII) CPTED analysis across access controls, surveillance, territorial reinforcement, maintenance, and activity support:

NATURAL SURVEILLANCE

40/100

HIGH

Findings:

Obstructed CCTV view due to tree.

ACCESS CONTROL

50/100

HIGH

Findings:

Lack of electronic access control systems.

TERRITORIAL REINFORCEMENT

60/100

MEDIUM

Findings:

Well-maintained perimeter fence.

MAINTENANCE

70/100

MEDIUM

Findings: Well-maintained entrance and landscaping.

ACTIVITY SUPPORT

50/100

HIGH

Findings: Lack of electronic visitor management.

13. Detailed Scene Analysis

(PCI) Scene #1: 989e513d-6141-4d3a-94fb-aed85f89f15d.png



Scene Analysis

OBSERVED CONDITIONS

Description	The image depicts the main entrance of the Clayton Jerde facility, featuring a security guard post, a manual boom barrier, and a perimeter fence. The entrance is landscaped with trees and shrubs, which partially obstruct the view of the CCTV camera.
Asset Inventory	Assets include a security guard, manual boom barrier, perimeter fence, and a CCTV camera.
Environmental Context	The entrance is located in a landscaped area with trees and shrubs, providing a pleasant aesthetic but obstructing the CCTV camera's view. The path is clear and well-maintained.
Observed Evidence	The entrance is open during business hours, with a security guard present but no electronic access controls.
Evidence Baseline	Visual evidence confirms the presence of a security guard, manual boom barrier, and perimeter fence but reveals gaps in electronic access control and CCTV coverage.

SECURITY ENGINEERING REVIEW

Existing Security Controls	Security controls include a guard post, a manual boom barrier, and a CCTV camera. The fence is in good condition.
Device Effectiveness	The CCTV camera is partially obstructed by a tree, reducing its effectiveness in monitoring the entrance. No electronic access control devices are visible.
Security Strengths	The presence of a security guard and manual boom barrier provides a basic level of access control.
Security Weaknesses	The lack of electronic access control and the obstructed CCTV camera are major weaknesses.
Engineering Review	The current setup provides minimal deterrent effect due to the lack of advanced access control systems. The obstructed CCTV camera limits surveillance capabilities.
Security Implications	Long-term implications include increased risk of unauthorized access and potential breaches due to gaps in surveillance and access control.
CPTED Evaluation	The CPTED evaluation indicates strong maintenance and territorial reinforcement but highlights weaknesses in natural surveillance and access control.

ATTACK SURFACE

Attack Opportunities	Potential attackers could exploit the open gate, bypass the manual boom barrier, and use the obstructed view of the CCTV camera to their advantage.
Attack Paths	Intruders may enter through the open gate during business hours, tailgate through the boom barrier, and remain undetected due to the obstructed CCTV camera.
Vulnerability Assessment	The assessment identifies vulnerabilities in surveillance and access control, requiring immediate attention.

BUSINESS & OPERATIONAL IMPACT

Business Consequences	Unauthorized access could lead to theft, vandalism, and safety risks, impacting operations and liability.
Risk Exposure & Impact	The impact is rated as medium due to the potential for unauthorized access and operational disruptions.
Image Risk Level	MEDIUM
Score Drivers & Influences	Positive Security Controls: Security Guard Presence (+) Provides basic deterrence. Risk Drivers: Obstructed CCTV View (-) Limits surveillance effectiveness. * Lack of Electronic Access Control (-) Increases unauthorized access risk.

CONSULTANT RECOMMENDATIONS

Recommended Mitigation	Reposition the CCTV camera, install electronic access controls, and implement a visitor management system.
Expected Risk Reduction	Implementing these improvements would significantly reduce the risk of unauthorized access.

Image Vulnerabilities

Obstructed CCTV View	MEDIUM
Lack of Electronic Access Control	HIGH

CPTED Breakdown

NATURAL SURVEILLANCE 40/100 High

FINDINGS: Obstructed CCTV view due to tree.

ACCESS CONTROL 50/100 High

FINDINGS: Lack of electronic access control systems.

TERRITORIAL REINFORCEMENT 60/100 Medium

FINDINGS: Well-maintained perimeter fence.

MAINTENANCE 70/100 Medium

FINDINGS: Well-maintained entrance and landscaping.

ACTIVITY SUPPORT 50/100 High

FINDINGS: Lack of electronic visitor management.

14. Assessor Dictation Notes

(PCII) The physical security auditor recorded the following voice dictation transcriptions and field observations during the walk-through:

AUDIO TRANSCRIPT

This image shows the main entrance of an industrial facility. A security guard is present at the gatehouse. A manual boom barrier controls vehicle entry. The perimeter fence appears to be in good condition. A CCTV camera is mounted near the entrance, but a large tree partially blocks the camera's field of view. No electronic access control system or visitor management kiosk is visible. The entrance gate appears to be open during normal operating hours.

(PCII) Key Spoken Findings:

- (PCII) A security guard is present at the gatehouse.
- (PCII) A manual boom barrier controls vehicle entry.
- (PCII) The perimeter fence appears to be in good condition.
- (PCII) A CCTV camera is mounted near the entrance.
- (PCII) A large tree partially blocks the camera's field of view.
- (PCII) No electronic access control system is visible.
- (PCII) No visitor management kiosk is visible.
- (PCII) The entrance gate appears to be open during normal operating hours.

CONSULTANT INTERPRETATION

The dictation confirms the presence of basic security controls but highlights significant gaps in electronic access and surveillance, which need immediate attention to mitigate unauthorized access risks.

AI Confidence: High

15. Vulnerability Register

(PCII) The following physical security vulnerabilities were detected, rated by severity class:

OBSTRUCTED CCTV VIEW

MEDIUM

Description:	The CCTV camera's field of view is partially blocked by a tree.
Evidence:	Tree partially blocks camera view.
Observation:	Camera placement needs adjustment for full coverage.
Analysis:	Obstruction makes undetected entry feasible.
Vulnerability Details:	Limited visibility at entrance.
Impact:	Reduced surveillance effectiveness.
Likelihood:	Medium
Recommended Mitigation:	Reposition camera to avoid obstruction.

ATTACK PATH

Exploitation Method:	Approach entrance where camera view is blocked.
Required Skill:	Novice
Attack Sequence:	Enter undetected due to obstructed view.
Probability of Success:	Medium
Detection Probability:	Low
Required Tools:	None
Time To Exploit:	Immediate

IMPLICATIONS

Operational Impact:	Compromised monitoring capabilities.
Business Impact:	Potential liability issues.
Security Impact:	Increased risk of unauthorized access.
Safety Impact:	Increased risk to personnel.
Escalation Path:	Potential access to sensitive areas.

RISK JUSTIFICATION

Likelihood Justification:	Obstruction makes undetected entry feasible.
Impact Justification:	Direct access to facility.
Severity Justification:	Medium due to surveillance gap.
Evidence Used:	Visible obstruction in image.
Rationale:	Obstruction reduces camera effectiveness.

LACK OF ELECTRONIC ACCESS CONTROL

HIGH

Description:	No electronic systems are in place to verify or control access.
--------------	---

Evidence:	No electronic access controls visible.
Observation:	Access relies on manual checks, which are less reliable.
Analysis:	Easy entry due to lack of controls.
Vulnerability Details:	Open access during business hours.
Impact:	Increased risk of unauthorized access.
Likelihood:	High
Recommended Mitigation:	Install electronic access control systems.

ATTACK PATH

Exploitation Method:	Enter through open gate without verification.
Required Skill:	None
Attack Sequence:	Walk through gate during open hours.
Probability of Success:	High
Detection Probability:	Low
Required Tools:	None
Time To Exploit:	Immediate

IMPLICATIONS

Operational Impact:	Increased liability and security risk.
Business Impact:	Risk of theft or vandalism.
Security Impact:	Potential for unauthorized access.
Safety Impact:	Increased risk to personnel.
Escalation Path:	Access to sensitive areas.

RISK JUSTIFICATION

Likelihood Justification:	Easy entry due to lack of controls.
Impact Justification:	High potential for unauthorized access.
Severity Justification:	High due to open access.
Evidence Used:	Open gate and lack of controls visible in image.
Rationale:	Open access presents high risk.

16. Remediation Action Roadmap

(PCII) Actionable physical security upgrades mapped by urgency level:

Immediate Priority

1 ACTIONS

- (PCII) Reposition CCTV camera to avoid obstruction. (Low Impact, Low Effort)

Recommended Priority

1 ACTIONS

- (PCII) Install electronic access control systems. (Low Impact, Low Effort)

Future Improvements

1 ACTIONS

- (PCII) Implement a visitor management system. (Low Impact, Low Effort)

IMMEDIATE (0-30 DAYS)

Reposition CCTV camera to avoid obstruction.

Location:	Main Entrance
Vulnerability Addressed:	Obstructed CCTV View
Rationale:	Improves surveillance coverage and effectiveness.
Business Impact:	Enhances security monitoring capabilities.
Security Impact:	Reduces undetected entry risk.
Implementation Effort:	Low
Expected Risk Reduction:	Significant reduction in risk of undetected entry.

SHORT-TERM (1-3 MONTHS)

Install electronic access control systems.

Location:	Main Entrance
Vulnerability Addressed:	Lack of Electronic Access Control
Rationale:	Ensures controlled and verified access.
Business Impact:	Reduces liability and enhances security.
Security Impact:	Prevents unauthorized access.
Implementation Effort:	Medium
Expected Risk Reduction:	Drastic reduction in unauthorized access risk.

LONG-TERM (3-12 MONTHS)

Implement a visitor management system.

Location:	Main Entrance
Vulnerability Addressed:	Lack of Visitor Management
Rationale:	Tracks and verifies visitors effectively.
Business Impact:	Enhances operational security and compliance.
Security Impact:	Improves accountability and tracking.
Implementation Effort:	Medium
Expected Risk Reduction:	Improves overall security management.

17. Security Controls Effectiveness

Access Control

Status:	Ineffective
Commentary:	No electronic systems to verify access.

Surveillance

Status:	Limited
Commentary:	Camera view obstructed, reducing effectiveness.

Detection

Status:	Ineffective
Commentary:	Limited by obstructed CCTV coverage.

Delay

Status:	Moderate
Commentary:	Manual barrier provides some delay.

Response

Status:	Moderate
Commentary:	Guard presence offers immediate response.

Barriers

Status: Moderate

Commentary: Manual boom barrier lacks electronic verification.

18. Security Gaps

Critical

Lack of Electronic Access Control

Risk Created: High exposure to unauthorized entry.

Likely Attack Enabled: Entering through open gate without verification.

Corrective Action: Install electronic access control systems.

High

Obstructed CCTV View

Risk Created: Reduced surveillance coverage.

Likely Attack Enabled: Undetected entry through obstructed areas.

Corrective Action: Reposition CCTV camera.

19. Security Maturity Benchmark

Current Level: Level 2 - Standard Commercial

Assigned Reasoning: Site implements basic security measures such as a guard and a boom barrier but lacks electronic systems.

Preventing Advancement: Absence of electronic access controls and obstructed surveillance coverage.

Required Controls To Advance: Install electronic access controls and reposition CCTV for full coverage.

Fastest Security Improvements

Reposition CCTV camera to avoid obstruction.

Effort: Low

Impact: High

ROI Justification: Improves surveillance coverage with minimal cost.

Install electronic access control systems.

Effort: Medium

Impact: High

ROI Justification: Drastically reduces unauthorized access risk.

20. Advanced Security Analysis

Environment Classification

Detected Environment

Environment Type: Facility

Confidence: 95%

Threat Model

Threat Assessment

Detected Threats: Unauthorized Access, Tailgating

Analysis Summary: The main threats include unauthorized access through open gates and tailgating due to lack of electronic access controls.

Physical Security Engineering

(PCI) The facility's physical security relies on manual processes and natural deterrents, which are insufficient for high-security needs. Recommendations focus on integrating electronic systems to bolster security.

Security Resilience

Intrusion Resistance

Score: 55 / 100

Reasoning: Manual controls offer basic deterrence but are easily bypassed.

Detection Capability

Score: 50 / 100

Reasoning: Obstructed CCTV limits detection.

Delay Capability

Score: 60 / 100

Reasoning: Manual barrier provides moderate delay.

Response Capability

Score: 65 / 100

Reasoning: Guard presence offers immediate response but lacks technological support.

Attack Vector Analysis

Unauthorized Access through Open Gate

Difficulty: Low

Likelihood: High

Detection: Low

Consequence: High

Mitigation: Install electronic access control systems.

Layered Defense Review

Deter Layer

Current State: Manual deterrents in place.

Strengths: Presence of guard and barriers.

Weaknesses: Lack of electronic systems.

Failure Scenarios: Intruders bypass manual checks.

Improvements: Integrate electronic deterrents.

Delay Layer

Current State: Manual barriers provide some delay.

Strengths: Boom barrier and fence.

Weaknesses: No electronic verification.

Failure Scenarios: Barrier bypassed during open hours.

Improvements: Automate barriers for improved delay.

Detect Layer

Current State: Limited by obstructed CCTV.

Strengths: CCTV presence.

Weaknesses: Obstructed view limits detection.

Failure Scenarios: Intruders remain undetected.

Improvements: Reposition CCTV for better coverage.

Respond Layer

Current State:	Guard presence provides immediate response.
Strengths:	Immediate human response.
Weaknesses:	No electronic support.
Failure Scenarios:	Limited response capability without technology.
Improvements:	Enhance response with electronic alerts.

(PCII) Weakest Layer: DETECT

Delay Detect Respond

DDR Assessment

Delay:	Medium
Detect:	Low
Respond:	Medium

(PCII) Current systems rely heavily on manual processes, limiting detection capabilities.

Likelihood vs Impact Matrix

Unauthorized Access

Likelihood:	High
Impact:	High
Priority:	Critical

Adversary Exploitation Scenarios

(PCII) Scenario 1: An intruder could exploit the open gate during business hours, bypass the manual boom barrier, and remain undetected due to the obstructed CCTV camera.

Control Failure Consequences

CCTV

Consequence:	Loss of surveillance coverage and increased risk of undetected intrusion.
--------------	---

21. Security Maturity & Defense Architecture

(PCII) Maturity Assessment: Current level 2 (Level 2 Commercial) -> Target level 3 (Level 3 Secured Facility)

(PCII) Gap Analysis:

(PCII) To advance from current to target level, the facility must integrate electronic access control and improve surveillance coverage.

(PCII) Layered Physical Security Review:

(PCII) DETER LAYER:

(PCII) Current State: Manual deterrents in place.

(PCII) Strengths: Presence of guard and barriers.

(PCII) Weaknesses: Lack of electronic systems.

(PCII) DELAY LAYER:

(PCII) Current State: Manual barriers provide some delay.

(PCII) Strengths: Boom barrier and fence.

(PCII) Weaknesses: No electronic verification.

(PCII) DETECT LAYER:

(PCII) Current State: Limited by obstructed CCTV.

(PCII) Strengths: CCTV presence.

(PCII) Weaknesses: Obstructed view limits detection.

(PCII) RESPOND LAYER:

(PCII) Current State: Guard presence provides immediate response.

(PCII) Strengths: Immediate human response.

(PCII) Weaknesses: No electronic support.

22. Exploitation Scenarios & Residual Risk

(PCII) Identified Adversary Attack Vectors:

- (PCII) Unauthorized Access through Open Gate (Difficulty: Low, Consequence: High)

(PCII) Post-Remediation Residual Risk Assessment:

- (PCII) Access Control -> Residual Risk: Unauthorized entry risk remains unless electronic systems are installed.

23. Assessment Conclusion

(PCII) The Clayton Jerde facility's perimeter security is currently at a moderate level, with significant areas for improvement. The most critical weakness is the lack of electronic access control systems, while the strongest existing control is the presence of a security guard. Implementing recommended improvements is expected to elevate the security rating to a higher standard, reducing unauthorized access risks and enhancing overall security resilience. The future security outlook is positive, with a strategic focus on integrating advanced technologies and maintaining a proactive security posture.



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

40 / 100

RISK CLASSIFICATION

HIGH RISK

EXECUTIVE DASHBOARD

SECURITY SCORE 40 / 100	RISK CLASSIFICATION HIGH RISK
ASSESSED MEDIA 1 Media	SECURITY DEVICES 0 Installed
FIELD DICTATIONS 0 Recorded	CPTED EVALUATED NO

1. Executive Summary

Security Posture

- (PCII) The current security posture of this sub-area is inadequate, with significant gaps in surveillance and access control mechanisms. The existing controls fail to meet the acceptable risk threshold, primarily due to the absence of electronic monitoring devices.

Environment Overview

- (PCII) The sub-area serves as a meeting room within a facility, characterized by a central table and seating for collaborative activities. Access appears to be unrestricted, with no visible barriers or entry controls. The physical layout is typical for such environments, but lacks security-enhancing features.

Threat Exposure

- (PCII) The primary threat vectors include unauthorized access and potential information leakage. Given the lack of surveillance, even low-skilled intruders could exploit these weaknesses. The likelihood of such events is heightened by the absence of deterrent measures.
- (PCII) 1. Lack of Surveillance: No visible cameras or monitoring devices, increasing vulnerability to unauthorized access. 2. Unrestricted Access: Open access points without barriers or access control increase the risk of intrusion. 3. Information Security Risks: The environment is prone to information leakage due to lack of secure communication measures.

Strategic Recommendations

- (PCII) Immediate investment in surveillance technology, such as cameras, is crucial to enhance monitoring capabilities. Implementing access control systems will significantly reduce unauthorized entry risks. These measures will improve operational security and protect sensitive information, justifying the investment with potential risk mitigation.

2. Device Analysis

(PCII) No electronic security devices are deployed in this sub-area, resulting in a significant monitoring gap. The absence of surveillance cameras or access control systems leaves the area vulnerable to unauthorized access and information breaches. Implementing cameras and access control systems would provide critical monitoring capabilities, reducing the risk of intrusion and enhancing overall security.

3. Detailed Scene Analysis

(PCI) Scene #1: mixkit-brainstorming-over-the-meeting-table-46680-hd-ready.mp4



Scene Analysis

OBSERVED CONDITIONS

Scene Overview	The image shows a meeting room with participants around a table.
Environmental Context	The room is enclosed with white brick walls, suggesting a formal meeting space.
Observed Evidence	Bright, natural lighting with a clean and organized table setup.
Evidence Baseline	The image confirms the absence of security controls in a meeting room environment.

SECURITY ENGINEERING REVIEW

Existing Security Controls	None visible.
Security Strengths	Controlled environment with limited entry points.
Security Weaknesses	No visible surveillance systems. • Open access without physical barriers.

BUSINESS & OPERATIONAL IMPACT

Risk Drivers	Absence of monitoring devices or access restrictions.
Operational Impact	Potential for unauthorized access and information leakage.
Image Risk Level	HIGH

CONSULTANT RECOMMENDATIONS

Consultant Recommendations	Install surveillance cameras. • Implement access control measures.
----------------------------	--

4. Vulnerability Register

(PCI) The following physical security vulnerabilities were detected, rated by severity class:

ABSENCE OF SURVEILLANCE SYSTEMS

HIGH

Description:	No visible cameras or monitoring devices in the video frames.
Evidence:	No visible cameras or monitoring devices in the video frames.
Likelihood:	High
Recommended Mitigation:	Install surveillance cameras to monitor activities.

UNRESTRICTED ACCESS

HIGH

Description:	Open access points without physical barriers observed in video frames.
Evidence:	Open access points without physical barriers observed in video frames.
Likelihood:	Medium
Recommended Mitigation:	Implement access control systems.

5. Remediation Action Roadmap

(PCII) Actionable physical security upgrades mapped by urgency level:

Immediate Priority

2 ACTIONS

- (PCII) Deploy surveillance cameras at strategic locations within the meeting room.
- (PCII) Install access control systems at entry points to restrict unauthorized entry.

IMMEDIATE

Deploy surveillance cameras at strategic locations within the meeting room.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

IMMEDIATE

Install access control systems at entry points to restrict unauthorized entry.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Significant improvement in access control.

6. Assessment Conclusion

(PCII) The current security posture of this sub-area is inadequate, with a high risk level due to the absence of surveillance systems and access controls. The environment lacks necessary security measures, making it vulnerable to unauthorized access and information leakage.

Critical Risks

The most urgent risks include the absence of surveillance systems and unrestricted access. These gaps significantly increase the likelihood of unauthorized activities and potential information breaches.

Primary Security Strengths

The controlled environment, with limited entry points, is a strength; however, it is undermined by the lack of effective security measures.

Business Impact Summary

The current security state poses a risk to business operations by exposing sensitive information and increasing the potential for unauthorized access. This could lead to financial losses and reputational damage if not addressed.

Expected Security Improvement

Implementing the recommended surveillance and access control measures is expected to significantly enhance security, raising the security score to 75 and reducing the risk level to Medium. This will improve monitoring, deter unauthorized access, and protect sensitive information.

Consultant Opinion

Addressing the identified vulnerabilities through immediate action is crucial for enhancing the security posture of this sub-area. The recommended measures will provide robust monitoring and access control, aligning the security state with acceptable risk thresholds.

Recommended Reassessment Interval

A reassessment is recommended within 6 months to ensure the effectiveness of implemented measures and to adjust strategies as necessary.



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

40 / 100

RISK CLASSIFICATION

HIGH RISK

EXECUTIVE DASHBOARD

SECURITY SCORE
40 / 100

RISK CLASSIFICATION
HIGH RISK

ASSESSED MEDIA
1 Media

SECURITY DEVICES
0 Installed

FIELD DICTATIONS
0 Recorded

CPTED EVALUATED
NO

1. Executive Summary

Security Posture

- (PCII) The current security posture of this sub-area is inadequate, with significant gaps in surveillance and access control mechanisms. The existing controls fail to meet the acceptable risk threshold, primarily due to the absence of electronic monitoring devices.

Environment Overview

- (PCII) The sub-area serves as a meeting room within a facility, characterized by a central table and seating for collaborative activities. Access appears to be unrestricted, with no visible barriers or entry controls. The physical layout is typical for such environments, but lacks security-enhancing features.

Threat Exposure

- (PCII) The primary threat vectors include unauthorized access and potential information leakage. Given the lack of surveillance, even low-skilled intruders could exploit these weaknesses. The likelihood of such events is heightened by the absence of deterrent measures.
- (PCII) 1. Lack of Surveillance: No visible cameras or monitoring devices, increasing vulnerability to unauthorized access. 2. Unrestricted Access: Open access points without barriers or access control increase the risk of intrusion. 3. Information Security Risks: The environment is prone to information leakage due to lack of secure communication measures.

Strategic Recommendations

- (PCII) Immediate investment in surveillance technology, such as cameras, is crucial to enhance monitoring capabilities. Implementing access control systems will significantly reduce unauthorized entry risks. These measures will improve operational security and protect sensitive information, justifying the investment with potential risk mitigation.

2. Device Analysis

(PCII) No electronic security devices are deployed in this sub-area, resulting in a significant monitoring gap. The absence of surveillance cameras or access control systems leaves the area vulnerable to unauthorized access and information breaches. Implementing cameras and access control systems would provide critical monitoring capabilities, reducing the risk of intrusion and enhancing overall security.

3. Detailed Scene Analysis

(PCI) Scene #1: mixkit-brainstorming-over-the-meeting-table-46680-hd-ready.mp4



Scene Analysis

OBSERVED CONDITIONS

Scene Overview	The image shows a meeting room with participants around a table.
Environmental Context	The room is enclosed with white brick walls, suggesting a formal meeting space.
Observed Evidence	Bright, natural lighting with a clean and organized table setup.
Evidence Baseline	The image confirms the absence of security controls in a meeting room environment.

SECURITY ENGINEERING REVIEW

Existing Security Controls	None visible.
Security Strengths	Controlled environment with limited entry points.
Security Weaknesses	No visible surveillance systems. • Open access without physical barriers.

BUSINESS & OPERATIONAL IMPACT

Risk Drivers	Absence of monitoring devices or access restrictions.
Operational Impact	Potential for unauthorized access and information leakage.
Image Risk Level	HIGH

CONSULTANT RECOMMENDATIONS

Consultant Recommendations	Install surveillance cameras. • Implement access control measures.
----------------------------	--

4. Vulnerability Register

(PCI) The following physical security vulnerabilities were detected, rated by severity class:

ABSENCE OF SURVEILLANCE SYSTEMS

HIGH

Description:	No visible cameras or monitoring devices in the video frames.
Evidence:	No visible cameras or monitoring devices in the video frames.
Likelihood:	High
Recommended Mitigation:	Install surveillance cameras to monitor activities.

UNRESTRICTED ACCESS

HIGH

Description:	Open access points without physical barriers observed in video frames.
Evidence:	Open access points without physical barriers observed in video frames.
Likelihood:	Medium
Recommended Mitigation:	Implement access control systems.

5. Remediation Action Roadmap

(PCII) Actionable physical security upgrades mapped by urgency level:

Immediate Priority

2 ACTIONS

- (PCII) Deploy surveillance cameras at strategic locations within the meeting room.
- (PCII) Install access control systems at entry points to restrict unauthorized entry.

IMMEDIATE

Deploy surveillance cameras at strategic locations within the meeting room.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

IMMEDIATE

Install access control systems at entry points to restrict unauthorized entry.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Significant improvement in access control.

6. Assessment Conclusion

(PCII) The current security posture of this sub-area is inadequate, with a high risk level due to the absence of surveillance systems and access controls. The environment lacks necessary security measures, making it vulnerable to unauthorized access and information leakage.

Critical Risks

The most urgent risks include the absence of surveillance systems and unrestricted access. These gaps significantly increase the likelihood of unauthorized activities and potential information breaches.

Primary Security Strengths

The controlled environment, with limited entry points, is a strength; however, it is undermined by the lack of effective security measures.

Business Impact Summary

The current security state poses a risk to business operations by exposing sensitive information and increasing the potential for unauthorized access. This could lead to financial losses and reputational damage if not addressed.

Expected Security Improvement

Implementing the recommended surveillance and access control measures is expected to significantly enhance security, raising the security score to 75 and reducing the risk level to Medium. This will improve monitoring, deter unauthorized access, and protect sensitive information.

Consultant Opinion

Addressing the identified vulnerabilities through immediate action is crucial for enhancing the security posture of this sub-area. The recommended measures will provide robust monitoring and access control, aligning the security state with acceptable risk thresholds.

Recommended Reassessment Interval

A reassessment is recommended within 6 months to ensure the effectiveness of implemented measures and to adjust strategies as necessary.



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
AREA NAME	Perimeter
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

70 / 100

RISK CLASSIFICATION

MEDIUM RISK

EXECUTIVE DASHBOARD

SECURITY SCORE

70 / 100

RISK CLASSIFICATION

MEDIUM RISK

ASSESSED MEDIA

2 Media

SECURITY DEVICES

1 Installed

FIELD DICTATIONS

0 Recorded

CPTED EVALUATED

YES

1. Executive Summary

Assessment Summary

- (PCII) The security assessment of the meeting room within the facility's perimeter reveals a moderately secure environment that relies heavily on natural surveillance and regular maintenance. The open layout of the room allows for oversight during meetings, contributing to its security strengths. However, the absence of visible security devices such as CCTV cameras and electronic access controls presents significant vulnerabilities. This lack of automated systems increases the risk of unauthorized access and limits the facility's ability to monitor and respond to security incidents effectively. Additionally, while the room is actively used for meetings, providing some natural surveillance, there is no security presence during non-meeting times, leaving the area vulnerable to unauthorized access. To enhance security, it is recommended to install surveillance cameras and electronic access control systems, improve external signage to reinforce territorial boundaries, and schedule regular security checks during non-peak hours. These measures are expected to significantly improve the security posture, aligning it more closely with industry standards for secured facilities. The projected outcome is a more robust security environment that reduces liability and ensures business continuity.

2. Facility Overview & Scope

(PCII) Facility Structure & Context:

(PCII) The facility is located at 742 Maple Ridge Lane, Austin, TX, and features a meeting room within its perimeter. The room is designed for collaborative activities, equipped with a large display screen and seating arrangements around a central table. The environment is well-lit and maintained, with plants contributing to a professional setting. The perimeter lacks visible surveillance and access control devices, indicating reliance on manual oversight for security. This setup is suitable for regular business operations but requires enhancements to meet higher security standards.

(PCII) Assessment Boundaries & Scope:

(PCII) The assessment focused on evaluating the security posture of the meeting room within the facility's perimeter through video analysis. The methodology involved analyzing nine frames extracted from a continuous video sequence, observing spatial relationships, access flow, and potential security gaps. The limitations include the absence of direct evidence of security devices and reliance on visual observations to infer security conditions.

3. Evidence Summary

(PCII) The video walkthrough provides a comprehensive view of the meeting room, showing active engagement and a well-maintained environment. The frames reveal an open layout conducive to natural surveillance but highlight the absence of automated security systems. Observations include the use of laptops and a presentation screen, with no visible access controls or surveillance devices. The evidence suggests a reliance on manual oversight, which presents risks during inactive periods.

4. Device Analysis

(PCII) No security devices such as CCTV cameras or electronic access controls were observed in the video, indicating a reliance on manual oversight for security. This absence presents significant vulnerabilities, as it limits the facility's ability to monitor activities and restrict unauthorized access effectively.



CCTV

Location:	Sub Area
Assessment:	The CCTV camera is positioned to cover a portion of the loading docks but leaves several areas unmonitored.
Effectiveness:	Medium

5. CPTED Analysis

(PCII) The CPTED assessment identifies several areas for improvement. Natural surveillance is limited by the absence of security cameras, and access control is weak due to the lack of electronic systems. Territorial reinforcement is adequate inside but lacks external indicators. Maintenance is strong, but emergency preparedness could be enhanced. Activity support is effective during meetings but requires additional measures during idle times. Recommendations include installing cameras, access controls, enhancing signage, and scheduling security checks.

6. Threat Scenarios

(PCII) Potential threat scenarios include unauthorized access during non-meeting times due to the absence of electronic access controls and surveillance devices. The lack of external signage and territorial indicators could lead to unintentional breaches, while the reliance on manual oversight increases the risk of security lapses.

7. Business Impact

Business Impact

Summary:

The identified security gaps could result in unauthorized access, leading to potential data breaches or disruptions in business operations. The absence of surveillance devices limits the ability to monitor and respond to incidents, increasing liability and potential financial losses. Enhancing security measures would mitigate these risks and align the facility with industry standards, reducing liability and ensuring business continuity.

8. Residual Risk

Residual Risk

Summary: After implementing the recommended improvements, residual risks include potential lapses during unforeseen circumstances or technological failures. Continuous monitoring and regular updates to security protocols will be necessary to address these residual risks effectively.

9. CPTED Security Snapshot

(PCII) CPTED analysis across access controls, surveillance, territorial reinforcement, maintenance, and activity support:

NATURAL SURVEILLANCE

60/100

MEDIUM

Findings: Limited visibility of access points; No visible surveillance devices

ACCESS CONTROL

50/100

HIGH

Findings: No visible access control mechanisms

TERRITORIAL REINFORCEMENT

65/100

MEDIUM

Findings: Clear signage and defined meeting space

MAINTENANCE

70/100

MEDIUM

Findings: Well-maintained environment

ACTIVITY SUPPORT

55/100

HIGH

Findings: Active meeting with engagement

10. Detailed Scene Analysis

(PCI) Scene #1: scene1frame_0.jpg

Visual evidence unavailable in offline context.

Scene Analysis

OBSERVED CONDITIONS

Scene Overview	The video walkthrough captures a meeting room setup with active engagement, highlighting the absence of visible security devices such as CCTV cameras or access controls. The room's open layout supports natural surveillance during meetings, but the absence of automated security systems presents vulnerabilities.
Environmental Context	Segments covered: Meeting Room Overview
Observed Evidence	Multiple individuals are seated around a table with laptops, engaged in a meeting with a large display screen in use. Frames show a meeting room with active engagement and a large display screen in use.
Evidence Baseline	The room's open layout supports natural surveillance during meetings, but the absence of automated security systems presents vulnerabilities. The video walkthrough captures a meeting room setup with active engagement, highlighting the absence of visible security devices such as CCTV cameras or access controls.

SECURITY ENGINEERING REVIEW

Security Weaknesses	No visible security surveillance devices. • Absence of electronic access control systems. • No visible surveillance cameras. • Absence of electronic access control systems.
---------------------	--

BUSINESS & OPERATIONAL IMPACT

Risk Drivers	Lack of CCTV coverage. • No automated access control.
Image Risk Level	MEDIUM

CONSULTANT RECOMMENDATIONS

Consultant Recommendations	Install surveillance cameras. • Implement electronic access control systems.
----------------------------	--

11. Vulnerability Register

(PCII) The following physical security vulnerabilities were detected, rated by severity class:

LACK OF SURVEILLANCE DEVICES

HIGH

Evidence:No visible CCTV cameras or surveillance devices.

Likelihood:High

Recommended Mitigation:Install CCTV cameras to provide continuous surveillance coverage.

ABSENCE OF ELECTRONIC ACCESS CONTROLS

MEDIUM

Evidence:No visible electronic access control systems.

Likelihood:Medium

Recommended Mitigation:Implement electronic access control systems to restrict unauthorized access.

12. Assessment Conclusion

(PCII) The assessment of the meeting room's security highlights the need for immediate improvements in surveillance and access control. By installing CCTV cameras and electronic access control systems, the facility can significantly enhance its security posture, reducing unauthorized access risks and aligning with industry standards. These measures will provide a more robust security environment, ensuring business continuity and reducing liability. Continuous monitoring and regular updates to security protocols will be essential to maintaining this improved security posture.



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

45 / 100

RISK CLASSIFICATION

HIGH RISK

EXECUTIVE DASHBOARD

SECURITY SCORE

45 / 100

RISK CLASSIFICATION

HIGH RISK

ASSESSED MEDIA

1 Media

SECURITY DEVICES

1 Installed

FIELD DICTATIONS

0 Recorded

CPTED EVALUATED

NO

1. Executive Summary

Security Posture

- (PCII) The current security posture of the Sub Area is inadequate, with significant vulnerabilities due to limited surveillance and unmanaged access points. The existing CCTV camera provides some coverage, but the overall security controls are insufficient to mitigate high-risk threats effectively.

Environment Overview

- (PCII) This Sub Area is a loading dock facility featuring multiple docks, a delivery truck, and storage items such as a dumpster and barrels. The environment is industrial, with several potential access points, including loading dock doors and adjacent areas.

Threat Exposure

- (PCII) The primary threats include unauthorized access and theft, facilitated by the open nature of the loading docks and limited surveillance. The skill level required to exploit these vulnerabilities is low, increasing the likelihood of incidents.
- (PCII) - Limited Surveillance: Only one CCTV camera is installed, providing inadequate coverage (Image ID 44). - Accessible Entry Points: Multiple loading docks and adjacent areas are potential unauthorized entry points (Image ID 44). - Unsecured Storage: The presence of a dumpster and barrels near the loading docks could be used to conceal criminal activity (Image ID 44).

Strategic Recommendations

- (PCII) Enhance security by installing additional CCTV cameras to cover all potential entry points and blind spots. Implement physical barriers or access control systems at loading docks to reduce unauthorized access. These measures will significantly improve the security posture and reduce operational risks associated with theft and unauthorized access.

2. Device Analysis

(PCII) The deployed CCTV camera is positioned to monitor the loading dock area, providing some level of surveillance. However, its effectiveness is limited by its singular placement, leaving multiple potential access points unmonitored. The camera's condition appears functional based on the available closeup image, but its coverage is insufficient for comprehensive security. Additional cameras are recommended to ensure full coverage and effective monitoring.



CCTV

Location:	Sub Area
Assessment:	The CCTV camera is positioned to cover a portion of the loading docks but leaves several areas unmonitored.
Effectiveness:	Medium

3. Detailed Scene Analysis

(PCI) Scene #1: ede01f89-ca62-4de9-84f2-fc2378fee41f.png



Scene Analysis

OBSERVED CONDITIONS

Scene Overview

The image shows a loading dock area with a delivery truck, a dumpster, and a CCTV camera.

Environmental Context

Industrial area with multiple loading docks and adjacent open spaces.

Observed Evidence

Concrete loading docks, a delivery vehicle, and unsecured barrels and dumpster.

Evidence Baseline

The image confirms limited surveillance and multiple unsecured access points.

SECURITY ENGINEERING REVIEW

Existing Security Controls	One CCTV camera mounted on the building wall.
Security Strengths	CCTV camera provides some surveillance.
Security Weaknesses	Limited camera coverage. • Multiple access points without physical barriers. • Unsecured items near access points.
Connected Devices	#1 CCTV Dome Camera

BUSINESS & OPERATIONAL IMPACT

Risk Drivers	Unmonitored access points. • Potential concealment of criminal activity.
Operational Impact	Increased risk of unauthorized access and theft, affecting operational security.
Image Risk Level	HIGH

CONSULTANT RECOMMENDATIONS

Consultant Recommendations	Install additional CCTV cameras to cover all access points. • Implement physical barriers or access control systems at loading docks. • Secure storage materials to prevent misuse.
----------------------------	---

4. Vulnerability Register

(PCII) The following physical security vulnerabilities were detected, rated by severity class:

LIMITED SURVEILLANCE COVERAGE

HIGH

Description:	Only one CCTV camera present, covering a limited area (Image ID 44).
Evidence:	Only one CCTV camera present, covering a limited area (Image ID 44).
Likelihood:	High
Recommended Mitigation:	Install additional cameras to ensure full coverage.

UNSECURED ACCESS POINTS

HIGH

Description:	Multiple loading docks without physical barriers (Image ID 44).
Evidence:	Multiple loading docks without physical barriers (Image ID 44).
Likelihood:	High
Recommended Mitigation:	Implement physical barriers or access control systems.

UNSECURED STORAGE MATERIALS

MEDIUM

Description:	Dumpster and barrels near loading docks (Image ID 44).
Evidence:	Dumpster and barrels near loading docks (Image ID 44).
Likelihood:	Medium
Recommended Mitigation:	Secure and monitor storage items.

5. Remediation Action Roadmap

(PCII) Actionable physical security upgrades mapped by urgency level:

Immediate Priority

2 ACTIONS

- (PCII) Install additional CCTV cameras to cover all loading dock areas and access points.
- (PCII) Implement measures to secure and monitor storage items near docks.

Recommended Priority

1 ACTIONS

- (PCII) Install physical barriers or implement access control at loading docks.

IMMEDIATE

Install additional CCTV cameras to cover all loading dock areas and access points.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

SHORT-TERM

Install physical barriers or implement access control at loading docks.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Substantial decrease in unauthorized entry risk.

MEDIUM-TERM

Implement measures to secure and monitor storage items near docks.

Vulnerability Addressed: VULN-3

Expected Risk Reduction: Moderate reduction in misuse risk.

6. Assessment Conclusion

(PCII) The security posture of the Sub Area is currently rated as high risk, primarily due to limited surveillance and unsecured access points. The presence of a single CCTV camera provides some monitoring; however, it is insufficient to cover the entire area effectively.

Critical Risks

The most urgent risks involve unauthorized access through unguarded loading docks and the potential for theft or unauthorized activities due to unsecured storage materials. Immediate action is required to mitigate these vulnerabilities.

Primary Security Strengths

The existing CCTV camera provides a foundational level of surveillance, which can be built upon to enhance the overall security infrastructure.

Business Impact Summary

The current security deficiencies pose a significant threat to business operations, with potential financial and reputational impacts from theft and unauthorized access. Addressing these vulnerabilities will protect assets and ensure operational continuity.

Expected Security Improvement

Implementing the recommended actions is expected to improve the security score to 75, reducing the risk level to medium. Enhanced surveillance and access control will significantly decrease the likelihood of security breaches.

Consultant Opinion

The Sub Area's security trajectory is positive, provided the recommended improvements are implemented promptly. These actions will address critical vulnerabilities and establish a more robust security framework.

Recommended Reassessment Interval

A reassessment should be conducted within 6 to 12 months to ensure the effectiveness of implemented measures and to identify any new vulnerabilities.



Physical Security Vulnerability Assessment

Report

CLIENT	Portland
SITE NAME	Clayton Jerde
DATE	July 21, 2026
ASSESSMENT ID	79

OVERALL SECURITY SCORE

45 / 100

RISK CLASSIFICATION

HIGH RISK

EXECUTIVE DASHBOARD

SECURITY SCORE

45 / 100

RISK CLASSIFICATION

HIGH RISK

ASSESSED MEDIA

1 Media

SECURITY DEVICES

1 Installed

FIELD DICTATIONS

0 Recorded

CPTED EVALUATED

NO

1. Executive Summary

Security Posture

- (PCII) The current security posture of the Sub Area is inadequate, with significant vulnerabilities due to limited surveillance and unmanaged access points. The existing CCTV camera provides some coverage, but the overall security controls are insufficient to mitigate high-risk threats effectively.

Environment Overview

- (PCII) This Sub Area is a loading dock facility featuring multiple docks, a delivery truck, and storage items such as a dumpster and barrels. The environment is industrial, with several potential access points, including loading dock doors and adjacent areas.

Threat Exposure

- (PCII) The primary threats include unauthorized access and theft, facilitated by the open nature of the loading docks and limited surveillance. The skill level required to exploit these vulnerabilities is low, increasing the likelihood of incidents.
- (PCII) - Limited Surveillance: Only one CCTV camera is installed, providing inadequate coverage (Image ID 44). - Accessible Entry Points: Multiple loading docks and adjacent areas are potential unauthorized entry points (Image ID 44). - Unsecured Storage: The presence of a dumpster and barrels near the loading docks could be used to conceal criminal activity (Image ID 44).

Strategic Recommendations

- (PCII) Enhance security by installing additional CCTV cameras to cover all potential entry points and blind spots. Implement physical barriers or access control systems at loading docks to reduce unauthorized access. These measures will significantly improve the security posture and reduce operational risks associated with theft and unauthorized access.

2. Device Analysis

(PCII) The deployed CCTV camera is positioned to monitor the loading dock area, providing some level of surveillance. However, its effectiveness is limited by its singular placement, leaving multiple potential access points unmonitored. The camera's condition appears functional based on the available closeup image, but its coverage is insufficient for comprehensive security. Additional cameras are recommended to ensure full coverage and effective monitoring.



CCTV

Location:	Sub Area
Assessment:	The CCTV camera is positioned to cover a portion of the loading docks but leaves several areas unmonitored.
Effectiveness:	Medium

3. Detailed Scene Analysis

(PCI) Scene #1: ede01f89-ca62-4de9-84f2-fc2378fee41f.png



Scene Analysis

OBSERVED CONDITIONS

Scene Overview

The image shows a loading dock area with a delivery truck, a dumpster, and a CCTV camera.

Environmental Context

Industrial area with multiple loading docks and adjacent open spaces.

Observed Evidence

Concrete loading docks, a delivery vehicle, and unsecured barrels and dumpster.

Evidence Baseline

The image confirms limited surveillance and multiple unsecured access points.

SECURITY ENGINEERING REVIEW

Existing Security Controls	One CCTV camera mounted on the building wall.
Security Strengths	CCTV camera provides some surveillance.
Security Weaknesses	Limited camera coverage. • Multiple access points without physical barriers. • Unsecured items near access points.
Connected Devices	#1 CCTV Dome Camera

BUSINESS & OPERATIONAL IMPACT

Risk Drivers	Unmonitored access points. • Potential concealment of criminal activity.
Operational Impact	Increased risk of unauthorized access and theft, affecting operational security.
Image Risk Level	HIGH

CONSULTANT RECOMMENDATIONS

Consultant Recommendations	Install additional CCTV cameras to cover all access points. • Implement physical barriers or access control systems at loading docks. • Secure storage materials to prevent misuse.
----------------------------	---

4. Vulnerability Register

(PCII) The following physical security vulnerabilities were detected, rated by severity class:

LIMITED SURVEILLANCE COVERAGE

HIGH

Description:	Only one CCTV camera present, covering a limited area (Image ID 44).
Evidence:	Only one CCTV camera present, covering a limited area (Image ID 44).
Likelihood:	High
Recommended Mitigation:	Install additional cameras to ensure full coverage.

UNSECURED ACCESS POINTS

HIGH

Description:	Multiple loading docks without physical barriers (Image ID 44).
Evidence:	Multiple loading docks without physical barriers (Image ID 44).
Likelihood:	High
Recommended Mitigation:	Implement physical barriers or access control systems.

UNSECURED STORAGE MATERIALS

MEDIUM

Description:	Dumpster and barrels near loading docks (Image ID 44).
Evidence:	Dumpster and barrels near loading docks (Image ID 44).
Likelihood:	Medium
Recommended Mitigation:	Secure and monitor storage items.

5. Remediation Action Roadmap

(PCII) Actionable physical security upgrades mapped by urgency level:

Immediate Priority

2 ACTIONS

- (PCII) Install additional CCTV cameras to cover all loading dock areas and access points.
- (PCII) Implement measures to secure and monitor storage items near docks.

Recommended Priority

1 ACTIONS

- (PCII) Install physical barriers or implement access control at loading docks.

IMMEDIATE

Install additional CCTV cameras to cover all loading dock areas and access points.

Vulnerability Addressed: VULN-1

Expected Risk Reduction: Significant reduction in unauthorized access risk.

SHORT-TERM

Install physical barriers or implement access control at loading docks.

Vulnerability Addressed: VULN-2

Expected Risk Reduction: Substantial decrease in unauthorized entry risk.

MEDIUM-TERM

Implement measures to secure and monitor storage items near docks.

Vulnerability Addressed: VULN-3

Expected Risk Reduction: Moderate reduction in misuse risk.

6. Assessment Conclusion

(PCII) The security posture of the Sub Area is currently rated as high risk, primarily due to limited surveillance and unsecured access points. The presence of a single CCTV camera provides some monitoring; however, it is insufficient to cover the entire area effectively.

Critical Risks

The most urgent risks involve unauthorized access through unguarded loading docks and the potential for theft or unauthorized activities due to unsecured storage materials. Immediate action is required to mitigate these vulnerabilities.

Primary Security Strengths

The existing CCTV camera provides a foundational level of surveillance, which can be built upon to enhance the overall security infrastructure.

Business Impact Summary

The current security deficiencies pose a significant threat to business operations, with potential financial and reputational impacts from theft and unauthorized access. Addressing these vulnerabilities will protect assets and ensure operational continuity.

Expected Security Improvement

Implementing the recommended actions is expected to improve the security score to 75, reducing the risk level to medium. Enhanced surveillance and access control will significantly decrease the likelihood of security breaches.

Consultant Opinion

The Sub Area's security trajectory is positive, provided the recommended improvements are implemented promptly. These actions will address critical vulnerabilities and establish a more robust security framework.

Recommended Reassessment Interval

A reassessment should be conducted within 6 to 12 months to ensure the effectiveness of implemented measures and to identify any new vulnerabilities.