

Di master tooling, untuk nomor tooling digit paling belakang 0 tidak bisa di baca di system approvel part tooling