
Chimney-side roof leak investigation

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2019-01

Summary

Intermittent bedroom ceiling stain traced to failed counterflashing and mortar joints on the chimney, separate from the 2017 garage flashing repair.

Observed Conditions / Findings

1. **ATTENTION** Water test reproduced leak at upper chimney counterflashing.
2. **INFO** Repointed deteriorated mortar joints.
3. **INFO** Installed new counterflashing and sealed reglet.
4. **INFO** Roof shingles noted as aged; recommend budgeting for replacement within 2-4 years.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2019-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.