

Air conditioner refrigerant leak service

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2020-04

Summary

Cooling performance complaint. System was low on R-22 refrigerant; leak indicators found at evaporator coil connection. Added reclaimed refrigerant after homeowner approved temporary repair.

Observed Conditions / Findings

- INFO** Suction pressure below target; superheat high.
- ATTENTION** Electronic leak detector indicated minor leak near indoor coil connection.
- INFO** Added 1.25 lb reclaimed R-22.
- INFO** Technician recommended planning replacement rather than major coil repair due to 18-year system age.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2020-04

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.