

Northstar Heating & Cooling (Demo)

317-555-0144 | dispatch@northstar-demo.example

License/ID: HVAC-DEMO-2371

Invoice

Document #: INV-2020-04-93

Date: 2020-07-22

Air conditioner refrigerant leak service

Customer Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address 1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID HIQ-DEMO-001
Event ID E2020-04

Work / Purchase Summary

Cooling performance complaint. System was low on R-22 refrigerant; leak indicators found at evaporator coil connection. Added reclaimed refrigerant after homeowner approved temporary repair.

Description	Amount
Labor / service	\$352.80
Materials / equipment	\$308.70
Trip, disposal, tax, permit, or misc.	\$73.50
TOTAL	\$735.00

Payment status: PAID IN FULL

Technician / Installer Notes

- Suction pressure below target; superheat high.
- Electronic leak detector indicated minor leak near indoor coil connection.
- Added 1.25 lb reclaimed R-22.
- Technician recommended planning replacement rather than major coil repair due to 18-year system age.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2020-04

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.