

Air conditioner capacitor failure

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2018-01

Summary

Outdoor unit would not start during high heat. Replaced failed dual-run capacitor and cleaned condenser coil.

Observed Conditions / Findings

- INFO** Existing 45/5 uF capacitor tested below tolerance.
- INFO** Installed Northstar NS45-5 capacitor.
- INFO** Compressor and fan amperage returned to normal after repair.
- INFO** Noted outdoor unit age: approximately 16 years.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Equipment Reference

Brand	Northstar Parts
Model	NS45-5
Serial	CAP18G1819
Warranty end	2019-07-18

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2018-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.