

Air conditioner capacitor failure

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2018-01

Coverage Record

Outdoor unit would not start during high heat. Replaced failed dual-run capacitor and cleaned condenser coil.

Product / Project	Air conditioner capacitor failure
Coverage	Limited parts / product coverage
Effective date	2018-07-18
Coverage end	2019-07-18
Registration / Event	E2018-01
Manufacturer	Northstar Parts
Model	NS45-5
Serial	CAP18G1819

Demo Warranty Terms

This fictitious warranty record is designed to let HouseIQ identify coverage dates, model and serial numbers, installer relationships, and warranty expiration. It is not a manufacturer warranty and conveys no real coverage.

- Existing 45/5 uF capacitor tested below tolerance.
- Installed Northstar NS45-5 capacitor.
- Compressor and fan amperage returned to normal after repair.
- Noted outdoor unit age: approximately 16 years.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2018-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.