

Chimney-side roof leak investigation

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2019-01

Coverage Record

Intermittent bedroom ceiling stain traced to failed counterflashing and mortar joints on the chimney, separate from the 2017 garage flashing repair.

Product / Project	Chimney-side roof leak investigation
Coverage	Limited parts / product coverage
Effective date	2019-04-06
Coverage end	See terms below
Registration / Event	E2019-01

Demo Warranty Terms

This fictitious warranty record is designed to let HouseIQ identify coverage dates, model and serial numbers, installer relationships, and warranty expiration. It is not a manufacturer warranty and conveys no real coverage.

- Water test reproduced leak at upper chimney counterflashing.
- Repointed deteriorated mortar joints.
- Installed new counterflashing and sealed reglet.
- Roof shingles noted as aged; recommend budgeting for replacement within 2-4 years.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2019-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.