
Basement water intrusion after heavy storm

Customer	Jordan & Casey Morgan (Fictitious Demo Homeowners)
Service address	1847 Cedar Hollow Way, Indianapolis, IN 46220
HouseIQ property ID	HIQ-DEMO-001
Event ID	E2020-01

Summary

After approximately 3.2 inches of rain, water entered at the northwest basement corner. Inspection found failed sump pump float and short downspout discharge contributing to saturation.

Observed Conditions / Findings

- INFO** Approximately 1/4 inch standing water limited to unfinished northwest utility area.
- INFO** Primary sump pump motor ran but float intermittently stuck.
- INFO** Northwest downspout discharged within 18 inches of foundation.
- INFO** Foundation crack at same wall was dry and appeared non-structural.

Recommendation

Follow the repair or maintenance recommendations described above and retain related invoices for a complete property history.

Recordkeeping note: Retain this document with related estimates, invoices, warranties, inspection reports, and manuals. HouseIQ demo event linkage: E2020-01

Entirely fictitious property, vendors, people, equipment, documents, and transactions created for HouseIQ software demonstration and testing.