

	D	irect	ion	Angle (RPM Modifier)		
MSB	LSB		Action	MSB	LSB	Value
0	0	0	no change	0	0	1
0	0	1	Left Slow	0	1	cosine(15°)
0	1	0	Left Med	1	0	cosine(22°)
0	1	1	Left Fast	1	1	cosine(30°)
1	0	0	no change			
1	0	1	Right Slow			
1	1	0	Right Med			

Right Fast

MS	SB	LSB	Action
0	0	0	Hover
0	0	1	Up Slow
0	1	0	Up Med
0	1	1	Up Fast
1	0	0	Hover
1	0	1	Down Slow
1	1	0	Down Med
1	1	1	Down Fast
			Į.

For every clock cycle increase/decrease rpm value by the following:
Slow increment by 2
Med increment by 8
Fast increment by 16

Note: I am taking a guess on the increment values. They may be too fast and if slow then adjust the increment values to something reasonable.