

Référence / Reference : Révision / Revision : A

Titre /Title: SDK 6.3 release delivery

Programme / Subject:

	Nom Name	Fonction Function
Etabli par : Vritten by:	P.Plasse	SDK project manager
	J.R. Poligny	project manager
/érifié ou Approuvé par : Checked or approved by:	C.Barthelemy	Export Product leader
Autorisé par : Authorized by:	C.Barthelemy	Export Product leader

Révision	Date de validité / d'application	Nb de pages	Nb de pages annexes	Objet et description de la modification
Issue	Validity/application date	Nb of pages	Nb of appendices	Object and description of modification
A	May 2009			Release SDK 6.3



1 INTRODUCTION

This document describes the content of the SDK 6.3 delivery and evolutions/corrections from SDK 6.2.2.

2 SDK

Evolutions

[FT 4782] TCPIP package is included inside SDK. Previously it was a separate package.

3 TELIUM SYSTEM

The Telium System delivery is the pack 7.73

• Telium Générique

[FT 3098]	Correction : to manage magstripe life counter on Booster 2
[FT 4219]	Evolution: add KEYBOAD in driver to manage ZKA
[FT 4416]	Evolution : possibility when few booster are connected to run few schemes in parallel.
[FT 4677]	Correction: on Telicapt to prevent blank line on printer

• ICT250 :

[FT 4595] Correction : on paper detection on ICT250 with GPRS option

Booster III: Main evolutions to Italia certification

[FT 4511]	Correction : on security frame not correctly managed
[FT 4669]	Correction: extend RSA exponent key length to more than 4 bytes in functions computing public key.

Driver GPRS

[FT 4603]

[FT 4604]

[FT 4153]	Evolution : the driver is able to provide hardware and firmware version of GPRS module Requested by LAR.
	To do that, use fioctl DGPRS_FIOCTL_GET_INFORMATION - module name is returned in field : module_identification - firmware version is returned in field : module_software_version
[FT 4602]	Correction: in case of MO200, return value "MO200" instead of "M0200" (M zero)

SMO/ Rév. : A Page : 1

Correction: to avoid bad synchronization between messages sent and received

Correction: module selection command \V1 was not correctly managed



[FT 4613] Evolution : GPRS driver is now able to provide SIM provider name.

ML30 / SMART 2: Main evolutions: requested by Germany

[FT 4438]	Evolution: Increase performance of IAPP (Thunder / booster communication)
[FT 4499]	Evolution: free RAM not used (128 bytes) by display driver.
[FT 4526]	Evolution: possibility to provide to schemes the following informations:
-	Booster1,2,3, Pin pad present/no and VardId

930 Morpho

[FT 4538] Evolution : on EFT930 Morpho : manage new extension board compatible with 930 BL1 and 930BL2

• MR40 - CAD30 UPT

[FT 4712]	Evolution: if the MR40 go into light sleep mode, card redraw don't wake-up the
	MR40
[FT 4713]	Correction on fast swipe linker with correction done on FT4626

4 TELIUM MANAGER

The Telium Manager delivery is the pack 52.00

[FT 4086]	Correction on Manager state ticket. Flash free is now correct.
[FT 4243]	Evolution on colour display :possibility to modify message font on - information message - get amount - Waiting card
[FT 4245]	Evolution : improve speed on C'Less
[FT 4320]	Evolution on Manager state ticket: print ZKA mode (yes/no) print accept previous version (yes/no)
[FT 4360]	Correction on message customisation : restore correct parameter Enable display header on EFTSmart Display header size Display header position high/low
[FT 4444]	Evolution : If default currency doesn't exist, use EURO as default
[FT 4550]	Evolution: use font and messages files in PGN format on ICT with functions LoadFont and LoadMSG

SMO/ Rév.: A Page: 2



[FT 4610] Correction on UCM on PinPad display management.

DLL Security 03.05 with evolutions/corrections

Add function SEC_SHA1Compute
Correction on SEC_RandomData
Speed optimisation on Telium 1
[FT 4683] correction to manage the 40 schemes with security DLL.

5 TCPIP

TCPIP package delivery is the pack 03.05

- Evolution: DLL SSL and DLL FTP are provided on Telium 1 and ICT format.

FTP:

FT 4537 Correction: bad Telium 2 signature

SSL

[FT 4208] Evolution : Add SHA-256 certificate management [FT 4307] Correction : manager serial number higher then 4 bytes.

[FT 4342] Correction: on function SSL New when the certificate is no correct.

6 LINKLAYER

[FT 4763] **MAJOR CORRECTION**: on function LL_GetHandle when the function is called to get PPP handle of GPRS (parameter LL_GET_HANDLE_GPRS) with Session handle == NULL.

7 SCHEMES

Neither evolution nor correction

8 TOOLS

No modification

SMO/ Rév.: A Page: 3