
Power Distribution Box (PDB)
Hot at all times
37 6 YE
4/0 BK
B
M
M
Crank motor solenoid
Fuse 12 Link BL
Fuse 12 Link BL
Fuse 12 Link BL
Fuse 12 Link BL
36 4 YE/WH
2037 4 RD
1/0 RD
1/0 RD
Battery
Battery
Battery
1/0 BK
1/0 BK
4/0 BK
B
G
Alternator
C122
Starter motor relay
570 4 BK/WH
2/0 BK
570 1 BK/WH
Frame ground stud
Engine block ground stud