COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Lamp or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Flash-to-Pass	10 and 7 10 and 6	Lever stalk pull and hold toward steering wheel.	Closed Circuit
Dimmer High Beam	10 and 7	Lever stalk away from steering wheel.	Closed Circuit
Dimmer Low Beam	10 and 6	Lever stalk in detent closest to steering wheel.	Closed Circuit
Turn Switch Circuit	10 and 8	Turn Switch to TURN LEFT and Hazard Switch to OFF.	Closed Circuit
	10 and 9	Turn Switch to TURN RIGHT and Hazard Switch to OFF.	Closed Circuit
Hazard Switch	10 and 8 10 and 9	Hazard Switch ON (Button depressed then released to FULL OUT position).	Closed Circuit