• **SUSPENSION—“KNOCKING” NOISE FROM REAR SUSPENSION OVER BUMPS—REVISED REAR COIL SPRINGS** • **NOISE—“KNOCKING” NOISE FROM REAR SUSPENSION OVER BUMPS—REVISED REAR COIL SPRINGS**	**Article No. 01-3-4**

MERCURY: 2001 COUGAR

ISSUE

Some 2001 Cougars may exhibit a “knocking” noise in the rear of the vehicle while going over bumps. This may be caused by an interference between the rear coil springs and the strut tower.

ACTION

Replace both rear coil springs with revised Spring (1S8Z-5560-BA) as instructed in the 2001 Cougar Workshop Manual, Section 204-02.

PART NUMBER	PART NAME
1S8Z-5560-BA	Coil Spring - Rear

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 304000, 702000, 702200

Copyright © 2001 Ford Motor Company