FOCUS INSTRUMENT PANEL FUSE COVER REPLACEMENT

AFFECTED VEHICLES: CERTAIN 2001 MODEL YEAR FOCUS ZX3

SERVICE PROCEDURE

1. Remove the instrument panel fuse cover and discard it. See Figure 1.



FIGURE 1

2. Install the ***new*** instrument panel fuse cover.

Ford Motor Company
CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
10/01