ELECTRICAL—RADIO—POOR AM RECEPTION

Article No. 02-20-6

LINCOLN: 2003 TOWN CAR

ISSUE

Some 2003 Town Car may exhibit poor AM radio reception. This may be caused by antenna wiring harness.

ACTION

Install 2003 Town Car AM Reception Service Kit part number 3W1Z-18K891-AA for standard wheel base and service kit part number 3W1Z-18K891-BA for long wheel base. Refer to instructions included with the kit to service.

PART NUMBER	PART NAME
3W1Z-18K891-AA	AM Reception Service Kit - Standard Wheel Base
3W1Z-18K891-BA	AM Reception Service Kit - Long Wheel Base

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022006A	Install AM Reception Filter Module Assembly Service Kit	1.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
18K891	X1

OASIS CODES: 203000, 203200, 207000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by “do-it-yourselfers”. Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company