Ford Motor Company

Service Recall Bulletin

July 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD – Advance Announcement of Safety Recall 00S18: Certain 2001 Model Year Escape Vehicles – Speed Control Cable and Servo Replacement

AFFECTED VEHICLES

Certain 2001 model year Escape vehicles equipped with V-6 engine and speed control, built at the Kansas City Assembly plant from October 22, 1999 through July 26, 2000.

REASON FOR THIS DELIVERY HOLD ANNOUNCEMENT

Affected vehicles are equipped with a speed control cable that may have a cracked or missing speed control cable servo cap locating tab. The potential exists for the locating tab to enter the servo clutch cavity and interfere with the speed control servo clutch.

Additionally, there is the potential for water to enter those units that contain a cracked or missing servo cap locating tab. This water could eventually cause corrosion that could potentially interfere with the function of the speed control.

Either condition could potentially not allow the throttle to return to idle when disengaging the speed control. If the speed control is used and either of the above conditions are present, a stuck throttle could result, which could potentially lead to a vehicle crash.

Do not drive, demonstrate, deliver or perform pre-delivery inspection **on any vehicles affected by this recall until this repair has been performed.**

Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to a buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $ 1,100 per vehicle.

Service repair instructions and parts requirements for Safety Recall 00S18 are currently under development.

VIN's will be activated on OASIS by Monday, July 31, 2000.

Affected vehicles are to be released from this hold only when the appropriate service repair has been completed.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs