Ann O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division



Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

February 9, 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Review of Unique Type of Service Action - Special Service Instruction (SSI)

REFERENCE: **See attached Special Service Instruction 00T06.**

The attached Dealer Bulletin details a unique type of service action - a "Special Service Instruction" (SSI). This type of service action was first introduced to dealers in June, 1997 with the release of SSI 97T01.

This type of service action is similar to an Owner Notification Program (ONP) in that affected vehicles will appear in OASIS and will be announced to you in a Dealer Bulletin format. This service action differs from an ONP in that there is no owner notification or involved vehicle listings. In addition, this type of service action is limited to the warranty coverage period for the specific involved part or system and claiming is done on the ACES II warranty screen rather than the recall screen.

Special Service Instructions are numbered similar to ONPs; they can be recognized by the "T" in the middle position of the program number. If a vehicle is in your dealership for other service requirements and OASIS indicates the vehicle is affected by one of these programs, the applicable SSI should be completed and the customer informed of the service performed.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Ford Motor Company

Ann O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

August 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Service Instruction 00T06: Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement

OASIS : Yes
OWNER LIST: **No**
OWNER LETTERS: **No**
PARTS RETURN: See Attachment II
PROGRAM TERMS: Through applicable 36 month / 36,000 miles warranty coverage only

AFFECTED VEHICLES

Certain 2001 Model Year Escape vehicles built at the Kansas City Assembly Plant from April 17, 2000 through July 26, 2000.

REASON FOR THIS SPECIAL SERVICE INSTRUCTION

Certain affected vehicles were built with a rear driveshaft that was produced with a CV joint shaft that may interfere with the CV boot. The interference may cause the CV joint boot to develop a hole, allowing contaminants to enter the CV joint, which may lead to CV joint failure. If the described condition exists, the contamination can lead to CV joint corrosion and a significant NVH concern.

SPECIAL SERVICE INSTRUCTION

Dealers are to replace the vehicle's rear driveshaft to correct this condition.

OWNER NOTIFICATION

There will be no owner notification from Ford Motor Company; this is a Special Service Instruction as part of applicable 36 month / 36,000 mile warranty service. Dealers should inform owners upon completion of this Special Service Instruction that their vehicle's rear driveshaft was replaced to ensure customer satisfaction.

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances
Attachment III:	Technical Information

QUESTIONS?

Claims Information:	1-800-423-8851
Other Program Questions:	1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

SPECIAL SERVICE INSTRUCTION: 00T06
Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this Special Service Instruction.

PLEASE NOTE

Correct all vehicles in stock before delivery.

PROMPTLY CORRECT

Promptly correct all affected vehicles at your dealership and other eligible vehicles which are brought to your dealership within the applicable 36 month / 36,000 mile warranty coverage period.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.

NOTE: Prepare and submit claims on the ACESII **warranty** screen rather than the ACESII recall screen.

- Use code information shown below:
    - Program Code – 00T06
    - Causal Component – 4602
    - Condition Code – 12
    - Labor Operation – Refer to Attachment II

SPECIAL SERVICE INSTRUCTION: 00T06
Certain 2001 Model Year Escape Vehicles – Rear Driveshaft Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Rear Driveshaft	00T06B	0.8 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through the Recall Hotline (1-800-325-5621). Parts will be shipped Priority Next Day delivery, beginning the week of August 28, 2000 once sufficient quantities of parts are available at the PDC's.

Part Number	Quantity per Repair	Description
YL8Z-4602-BH	1	Driveshaft, Rear
YL8Z-4N272-AA	4	Bolt, Retainer (Sold 4 bolts to a package. One package will complete 1 vehicle)
W705891-S301	2	Nuts, Center Bearing Retaining (Sold 4 nuts to a package. One package will complete 2 vehicles)

NOTE: Removed parts must be mutilated and properly scrapped to prevent their use on another vehicle.

ORDER INFORMATION DOR/COR

DOR/COR number 50175 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.