Ford Motor Company

Frank M. Ligon
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

02L10 August 2002

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that certain 2000 model year 4x2 Expedition vehicles fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 120.

The tire inflation pressures for the rear tires listed on the Certification Label of your Expedition may be incorrectly stated. We apologize for this inconvenience and want to assure you that we are dedicated to correcting this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…

A Certification Label with incorrect rear tire inflation pressure information may have been installed on your Expedition. Ford Motor Company is providing a supplemental label with correct tire information.

What *Ford Motor Company* and your dealer will do…

Please attach the enclosed Supplemental Tire Information Label to your Expedition. To install the label yourself, use the instructions provided with this letter. If you prefer, your Ford or Lincoln Mercury dealer will install the label for you at no charge.

If you wish to have your dealer install the label, call your dealer and request an appointment to have Field Service Action 02L10 performed on your Expedition.

On your appointment date bring this letter and the label to your dealer. If you lose your label, let your dealer know when you request an appointment, so another label can be ordered. If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

If you've changed address or sold the vehicle...

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner.

© Copyright 2002 Ford Motor Company

If you have questions…

If you have questions or need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Or you may contact us through the Internet …

Hearing impaired call (800) 232-2952. TDD for the hearing impaired.

www.ownerconnection.com

If you are still having trouble getting your Expedition repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. We stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your Expedition maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Frank M. Ligon

Frank M. Ligon
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

SUPPLEMENTAL TIRE INFORMATION LABEL

AFFECTED VEHICLES: CERTAIN 2000 MODEL YEAR EXPEDITION 4X2 VEHICLES

SERVICE PROCEDURE

- Open the driver's door.
- Locate the original vehicle certification label on the side of the driver's door.

1. Clean the area below the vehicle certification label using isopropyl alcohol (commonly referred to as rubbing alcohol) and a clean rag.
2. Remove any non-permanent labels such as oil change labels, if necessary. If there are any other permanent labels in this location, clean an area large enough to allow for full adhesion.
3. Allow the area to dry completely.
4. Peel the backing off the ***new*** supplemental tire information label and install it as shown. See Figure 1.
5. Check the tire air pressure on all of the tires and adjust to specifications, if required.




FIGURE 1

Ford Motor Company

CPR © 2002 FORD MOTOR COMPANY

DEARBORN, MICHIGAN 48121
08/02