NOISE—"THUMPING" FROM THE A/C SYSTEM DURING COLD ENGINE STARTUP—VEHICLES BUILT THROUGH 11/29/1999	Article No. 99-24-6

FORD: 1999-2000 SUPER DUTY F SERIES

ISSUE

A "thumping" noise from the A/C system may be heard during cold engine start. This may be caused by liquid present in compressor during startup.

ACTION

Replace the A/C accumulator with revised Accumulator (YL3Z-19C836-BA). Refer to the 1999 Super Duty F-Series Workshop Manual, Section 412, for A/C accumulator removal and installation procedures.

PART NUMBER	PART NAME
YL3Z-19C836-BA	Accumulator

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
992406A	Replace Accumulator	1.2 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
19C836	07

OASIS CODES: 208000, 702000, 702100, 702300