Related Newsletter Articles

01S24/01S25 – Wiper Motor Gear Cover Installation Tips

09/03/2001

When installing the wiper motor gear cover, it is not necessary to hear an audible "click" sound as each and every locking tab engages its motor housing mounting lug.

Pay close attention to locking "tab E" engagement. A partial engagement with the motor housing mounting lug **is acceptable** as shown in 01S24 Figure 11 of Attachment III or 01S25 Figure 9 of Attachment III. It is not necessary to replace the wiper motor assembly if the cover is firmly latched to the housing.

01S24 - 01S25 Windshield Wiper Cover

08/06/2001

Fordstar will broadcast the 01S24-01S25 Wiper Gear Cover replacement video beginning August 16th. The tape is 9 minutes long and will be broadcast 3 times in the half-hour period. The current schedule is listed below.

Date	Start Time	End Time	Channel USA	Channel Canadian
09/04/2001	13:00:00	13:30:00	C107	C707
09/05/2001	09:00:00	09:30:00	C106	C706
09/07/2001	15:30:00	16:00:00	C106	C706
09/11/2001	16:30:00	17:00:00	C106	C706
09/12/2001	13:30:00	14:00:00	C107	C707
09/13/2001	18:00:00	18:30:00	C107	C707

Seed stock of part # 1F2Z-17D532-CA is being shipped to involved dealers as a stock order. Please watch for its delivery.

Important: Part #XS4Z-17D532-BA for Focus vehicles will not be available until September 14th. For Focus, in emergency cases, please contact the Special Service Support Center. Customer mailings will be delayed to permit arrival of parts.

Copyright © 2001 Ford Motor Company
Published By: **Recall/Service Programs Department**
Ford Customer Service Division