BUMPER—FRONT BRACKET REPLACEMENT—SERVICE TIP	Article No. 99-20-3

FORD: 1995-2000 EXPLORER

MERCURY: 1997-2000 MOUNTAINEER

ISSUE

front end, the front frame horn or the entire frame is being replaced when only the front bumper bracket is damaged on some vehicles. A new Service Kit has been made available to replace front bumper brackets only.

ACTION

Replace front bumper brackets, if necessary, during front end repair. Refer to the procedure outlined on the Instruction Sheet in the Front Bumper Bracket Service Kit.

NOTE

THIS KIT IS FOR FRONT BUMPER BRACKET REPLACEMENT ONLY. IT IS DESIGNED FOR UNDAMAGED FRONT FRAME RAILS.

PART NUMBER	PART NAME
F57Z-17N775-AA	Front Bumper Bracket Kit - RH (1995-1998)
F57Z-17N775-BA	Front Bumper Bracket Kit - LH (1995-1998)
XL2Z-17N775-AA	Front Bumper Bracket Kit - RH (1999-2000)
XL2Z-17N775-BA	Front Bumper Bracket Kit - LH (1999-2000)

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 108000, 111000, 305000