Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 00L09 – Certain 1991 – 2001 Explorer and 1997 – 2001 Mountaineer and 2001 Explorer Sport Trac and Explorer 2-Door Sport Vehicles - Supplemental Tire Inflation Label

OASIS: No – Labels will be mailed directly to owners
OWNER LIST: No
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until March 31, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain Explorer vehicles produced with P235/75 R15 tires built at the St. Louis or Louisville assembly plants from beginning of production of the 1991 model year through 2001 model year with a build date of September 24, 2000 or before.

Certain Mountaineer vehicles produced with P235/75 R15 at the St. Louis Assembly Plant from beginning of production of the 1997 model year through 2001 model year with a build date of September 24, 2000 or before.

Certain Explorer Sport Trac and Explorer 2-Door Sport vehicles produced with P235/75 R15 tires at the St. Louis Assembly Plant from beginning of production of the 2001 model year through September 24, 2000.

REASON FOR THIS ACTION

The recommended inflation pressure for 15" Firestone P235/75 R15 tires on the affected vehicles is being revised at the request of Bridgestone/Firestone, Inc. The recommended pressures that were below 30 psi are being raised to 30 psi. The recommended tire pressure for those vehicles originally equipped with other tires remains as specified on the certification label on the driver's door.

SERVICE ACTION

Owners of the affected vehicles will be sent a label to install below the certification label on the driver's door. The owner may attach the label on their own or take the vehicle to a Ford or Lincoln Mercury Dealer and have them install the label (see Attachment III).

ADDITIONAL LABELS

To assist customers who prefer to have this service completed at the dealership and arrive without the label, please call the Recall Hotline at 1-800-325-5621 to obtain more labels.

NOTE: 2001 model Explorer Sport Trac takes a different label from the other affected vehicles (see Attachment II and Attachment III).

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other Recall Questions:……..1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Special Field Action 00L09
Explorer and Mountaineer Vehicles
Supplemental Tire Inflation Label

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

Special Field Action 00L09
Explorer and Mountaineer Vehicles
Supplemental Tire Inflation Label

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install label below the existing label on the driver's door for customer, if requested or in stock unit.	00L09B	0.2 Hrs.

PARTS REQUIREMENTS

Ordering Instructions for Additional Labels

The supplemental tire inflation labels for this program are being sent directly to customers of the affected vehicles. Additional labels may be ordered by calling the Recall Hotline at 1-800-325-5621. Inform the operator you are calling in regard to Special Field Action 00L09. Be prepared to provide your name, address, dealer P & A code, and vehicle(s) you need label(s) for.

NOTE: There are two different labels. Affected Explorer/Mountaineer and Explorer 2-Door Sport 1991 through 2001 model year label will have recommended pressure of 30 psi front and 30 psi rear. Affected Explorer Sport Trac 2001 model year label will have 30 psi front and 35 psi rear.

DEALER PRICE

Dealers will not be charged for the supplemental safety certification labels ordered under this program.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

00L09

Your Vehicle Identification Number: 12345678901234567
Explorer/Mountaineer & Explorer 2-Door Sport owner letter

Mr. John Sample:

Ford Motor Company is revising the recommended tire inflation pressure on your vehicle if your vehicle is equipped with Firestone P235/75 R15 tires. Bridgestone/Firestone, Inc. has requested that Ford revise the recommended tire pressure to 30 psi. For vehicles originally equipped with other tires, the recommended tire pressure remains as specified on the certification label on the driver's door.

What Ford Motor Company is asking you to do…

We have enclosed a label that will serve as a reminder that if your vehicle is equipped with Firestone P235/75 R15 tires the new recommended inflation pressure for these tires is 30 psi (207 KPa) front and 30 psi (207 KPa) rear. This label is designed to be installed below the certification label on the driver's door of your vehicle. The back of this letter has instructions for installing the label.

What *Ford Motor Company* and your dealer will do…

To install the label yourself, use the instructions printed on the reverse of this letter. If you prefer, your Ford or Lincoln Mercury dealer will install the label for you at no cost.

If you wish to have your dealer install the label, call your dealer and request an appointment to have Special Service Program 00L09 performed on your vehicle. On your appointment date bring this letter and the label to your dealer. If you lose your label, let your dealer know when you request an appointment, so another label can be ordered.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have questions or need assistance, please contact the Ford Motor Company North American Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8am - 11pm (Monday-Friday) ET
9am - 6pm (Saturday) ET

OR

You may contact us through the Internet at:
www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this notification, we stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

00L09

Your Vehicle Identification Number: 12345678901234567
2001 Explorer Sport Trac owner letter

Mr. John Sample:

Ford Motor Company is revising the recommended tire inflation pressure for your vehicle if your vehicle is equipped with Firestone P235/75 R15 tires. Bridgestone/Firestone, Inc. has requested that Ford revise any recommended tire pressures to a minimum of 30 psi. For vehicles originally equipped with other tires, the recommended tire pressure remains as specified on the certification label on the driver's door.

What Ford Motor Company is asking you to do…

We have enclosed a label that will serve as a reminder that if your vehicle is equipped with Firestone P235/75 R15 tires the new recommended inflation pressures for these tires is 30 psi (207 KPa) front and 35 psi (241 KPa) rear. This label is designed to be installed below the certification label on the driver's door of your vehicle. The back of this letter has instructions for installing the label.

What *Ford Motor Company* and your dealer will do…

To install the label yourself, use the instructions printed on the reverse of this letter. If you prefer, your Ford or Lincoln Mercury dealer will install the label for you at no cost.

If you wish to have your dealer install the label, call your dealer and request an appointment to have Special Service Program 00L09 performed on your vehicle. On your appointment date bring this letter and the label to your dealer. If you lose your label, let your dealer know when you request an appointment, so another label can be ordered.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have questions or need assistance, please contact the Ford Motor Company North American Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8am - 11pm (Monday-Friday) ET
9am - 6pm (Saturday) ET

OR

You may contact us through the Internet at:
www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this notification, we stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs