• **DRIVEABILITY—NO START, LOSS OF POWER OR ROUGH IDLE—DURING EXTREME COLD WEATHER OPERATION—FUEL GELLING—VEHICLES EQUIPPED WITH 7.3L ENGINE** • **FUEL—NO START, LOSS OF POWER OR ROUGH IDLE—DURING EXTREME COLD WEATHER OPERATION—FUEL GELLING—VEHICLES EQUIPPED WITH 7.3L ENGINE**	**Article No. 01-4-4**

FORD: 1999-2001 SUPER DUTY F SERIES
2000-2001 EXCURSION

ISSUE

Fuel quality and moisture in certain diesel fuels may cause some vehicles to exhibit a no start, gradual loss of power, or a rough idle condition due to fuel gelling during extreme cold weather operation.

ACTION

Add Top Water Fuel Heater Service Kit (1C3Z-9J294-AA) to increase return fuel temperature which in turn increases bulk fuel temperature in the tank. Instructions and parts for the repair procedure are included in the kit.

PART NUMBER	PART NAME
1C3Z-9J294-AA	Service Kit - Top Water Fuel Heater

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 404000, 602300, 603000, 607000, 607400, 608000, 608400, 608500, 609000, 609400, 609500, 614000, 614500, 614600

Copyright © 2001 Ford Motor Company