AIR CONDITIONING—INCORRECT R-134A CHARGE LEVEL LABEL—VEHICLES BUILT 10/4/1999 THROUGH 12/6/1999	Article No. 00-5-2

FORD: 2000 TAURUS

MERCURY: 2000 SABLE

ISSUE

A label with the incorrect R-134a refrigerant charge level was installed on some vehicles. All vehicles left the assembly plants with the correct charge level of R-134a refrigerant.

ACTION

When servicing the A/C system on an affected vehicle within the build date range, the correct R-134a refrigerant charge is 0.96kg (34 oz), NOT 0.79kg as the refrigerant charge capacity may read.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 208000, 208999