Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 00L07 – Certain 1998 through 2000 Model Year E-Series and F-Series Bi-Fuel CNG Vehicles – Fuel Door Label Application / Replacement

OASIS : No – Labels will be mailed directly to owners
OWNER LIST: No
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until April 30, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain 1998 model year E250 and E350 Series Bi-Fuel CNG vehicles built at the Lorain Assembly Plant and modified by GFI Control Systems from January 22, 1998 through October 12, 1998.

Certain 1999 model year E250 and E350 Series Bi-Fuel CNG vehicles built at the Lorain Assembly Plant and modified by GFI Control Systems from October 21, 1998 through November 16, 1999.

Certain 1998 model year F150 and F250 Series Bi-Fuel CNG vehicles built at the Kansas City Truck Plant and modified by GFI Control Systems from January 12, 1998 through December 31, 1998.

Certain 1999 model year F150 and F250 Series Bi-Fuel CNG vehicles built at the Kansas City Truck Plant and modified by GFI Control Systems from February 23, 1999 through November 16, 1999.

Certain 2000 model year F150 Series Bi-Fuel CNG vehicles built at the Ontario Truck Plant and modified by GFI Control Systems at the Cambridge, Ontario facility from October 12, 1999 through September 20, 2000.

NON-COMPLIANCE

The label affixed at the fuel filler door during vehicle modification contains the inspection date and expiration date of the CNG tank, however it does not contain the statement "See instructions on the fuel container for inspection and service life". Federal Motor Vehicle Safety Standard (FMVSS) No. 303 specifies that this statement be provided on a permanent label near the vehicle refueling connection, therefore the vehicles do not comply with this requirement.

SERVICE ACTION

A label that complies with Federal Motor Vehicle Safety Standard (FMVSS) No. 303 and contains the correct statement will be mailed directly to owners of affected vehicles. Owners will be provided instructions to affix the compliant label on the fuel door. However, if the owner chooses to have the label installed by a dealer, this service may be performed by dealership service personnel.

ADDITIONAL CERTIFICATION LABELS

To assist customers who prefer to have this service completed at the dealership and arrive without the label, please call the Recall Hotline at 1-800-325-5621 to obtain copies of the label.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Label Installation Instruction
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other Recall Questions:……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Special Field Action 00L07
Certain 1998 through 2000 Model Year E-Series and F-Series Bi-Fuel CNG Vehicles – Fuel Door Label Application / Replacement

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

Special Field Action 00L07
Certain 1998 through 2000 Model Year E-Series and F-Series Bi-Fuel CNG Vehicles – Fuel Door Label Application / Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install new label for customer, if requested	00L07B	0.2 Hrs.

PARTS REQUIREMENTS

Ordering Instructions for Additional Compliance Labels

Federal Motor Vehicle Safety Standard (FMVSS) No. 303 compliant fuel door labels (Part Number L1-498) for this program are being sent directly to owners of affected vehicles.

Additional labels may be ordered by calling the Recall Hotline at 1-800-325-5621. Inform the operator you are calling in regard to Special Field Action Program 00L07. Be prepared to provide your name, address, dealer P & A code, and how many labels you need.

DEALER PRICE

Dealers will not be charged for the supplemental safety certification labels ordered under this program.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

November 2000

00L07

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company has decided that certain 1998 through 2000 E-Series and F-Series Bi-Fuel CNG vehicles fail to conform to the requirements specified in the Federal Motor Vehicle Safety Standard (FMVSS) No. 303.

Although this does not affect your vehicle's performance, we are required to correct this non-conformance. We apologize for this inconvenience and want to assure you that we are dedicated to correcting this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…	A compliance label that is required on your vehicle's fuel door may not have been installed during modification. Also, some vehicles have a label on the fuel door, but it does not contain the statement "See instructions on the fuel container for inspection and service life", as required by Federal Motor Vehicle Safety Standard (FMVSS) No. 303.
What *Ford Motor Company* and your dealer will do…	Enclosed is a label that complies with Federal Motor Vehicle Safety Standard (FMVSS) No. 303. This label is to be placed on the inside of your vehicle's fuel door. The compliance label is provided free of charge. To install the label yourself, please refer to the enclosed instructions. If you prefer, your dealer will install this label for you at no cost.
If you've changed address or sold the vehicle…	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly without charge, please contact the Ford Motor Company North American Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8:00 AM - 11:00 PM (Monday-Friday) ET
9:00 AM - 6:00 PM (Saturday) ET

or you may contact us through the Internet at:
www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this notification, we stand committed with our Ford dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.


We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

LABEL INSTALLATION

- Open the fuel filler door.
- Clean the **inside lower half** of the fuel filler door, using the supplied alcohol wipe or isopropyl alcohol and a clean rag. If there is another label in this location, it does not have to be removed. The ***new*** label can be applied directly over it.
- Allow the area to dry completely.
- Peel the backing from the ***new*** compliance label and install it as shown in the illustration below.



CPR © 2000 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
10/00