COMPLIANCE LABEL

AFFECTED VEHICLES: **CERTAIN 1998 - 2000 E-SERIES AND F-SERIES BI-FUEL CNG VEHICLES**

SERVICE PROCEDURE

1. Open the fuel filler door and clean the inside lower half of the door, using the supplied alcohol wipe or isopropyl alcohol and a clean rag. If there is another label in this location, it does not have to be removed. Allow the area to dry completely.
2. Peel the backing from the ***new*** compliance label and install it as shown in the illustration below.



FIGURE 1

CPR © 2000 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
10/00