SSI	Number 02T08	2001/2002 Ranger PCM Recalibration Product Enhancement
Date: September 2002		

Model Year	Model	Assembly Plant	Vehicle Build Date Range	Coverage Terms
2001/2002	Ranger equipped w/2.3L	Twin Cities and Edison	Certain vehicles built from 8/23/2000 – 10/4/2001	36 months/36,000 miles (36 months/50,000 miles California Cert)

OASIS Activation	Yes, you must use OASIS to determine if a vehicle is eligible for this Special Service Instruction.
Involved Unit Listing	Yes, list will include in-stock units identified by Ford Motor Company as of the date this SSI was issued. Promptly correct all affected in-stock units, as identified on your dealer Online Involved Unit Listing available on QCDealer.com.
Customer Satisfaction Opportunity	Correct affected vehicles identified in OASIS, which are brought to your dealership **within the applicable new vehicle warranty coverage period.** This is an opportunity to provide additional warranty service for customers who use your service department. Because customers will not be expecting this service, before performing the repair, dealers should inform owners that this service will be performed on their vehicle to improve their overall satisfaction. Upon completion of this SSI, the customer must be provided with a written repair order that confirms what specific services (parts and labor) were performed.
Rental Vehicles	Rental vehicle coverage is not approved for this SSI.

Issue

In some of the affected vehicles, the OBD Evaporative Emission Monitor calibration has reduced capability to detect some fuel vapor leaks such as a fuel cap off and may not illuminate the MIL as required by regulations.

Action

On all affected vehicles, dealerships are instructed to reflash the PCM. (See Technical Instructions on next page.)

© Copyright 2002 Ford Motor Company

SSI Number 02T08: 2001/2002 Ranger
PCM Recalibration
Product Enhancement

Administrative Details

Claims Preparation and Submission	**Note:** Please prepare and submit claims on the ACESII **warranty** screen rather than the ACESII recall screen. • Enter claims using DWE. • Refer to ACESII Manual for claims preparation and submission information. • Use code information shown below: • Claim Code – 02T08 • Causal Component – RECALEM • Condition Code – 42 • Labor Operation – 02T08A or B • Customer Concern Code – D50

	Description	Labor Operation	Labor Time
Labor Allowances	Vehicle already Flashed to latest level	02T08A	0.3 hr
	Reflash vehicle PCM	02T08B	0.4 hr

	Description	Part Number	Quantity
Parts Requirements	Authorized Modification Label* (no charge)	FPS-8262	1

* Label orders come in packages of 25

Questions?	Claims Information: 1-800-423-8851 Special Service Support Center: 1-800-325-5621

Technical Instructions	See next pages

© Copyright 2002 Ford Motor Company