• HEADLAMP—MOISTURE IN LENS ASSEMBLY • TAILLAMP—MOISTURE IN LENS ASSEMBLY	Article No. 99-22-7

FORD: 2000 TAURUS

MERCURY: 2000 SABLE

ISSUE

Moisture/condensation may be visible in the headlamp or taillamp outer edge areas after washing or rainfall. This may occur because this area is outside the sealed portion of the lamp body.

ACTION

No repair or replacement should be performed. The moisture will dry when driving or when exposed to sunlight.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 102000, 201000, 201200, 203000