Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

February 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Field Service Action 02L08: Certain 1999/2000 Model Year F-Series vehicles over 8500 GVWR equipped with 5.4L/6.8L engines – Missing Important Engine Information Label

OASIS: No – Supplemental Important Engine Information labels will be mailed to owners.
OWNER LIST: No
PROGRAM TERMS: This program will be in effect until August 31, 2002, regardless of mileage.

VEHICLES COVERED BY THIS ACTION

Certain 1999/2000 model year F-Series vehicles over 8500 GVWR equipped with 5.4L/6.8L engines. The affected vehicles were built at:

1999 Model Year Vehicles

- Kentucky Truck Assembly Plant from October 20, 1997 through March 19, 1999
- Cuautitlan Assembly Plant from October 13, 1998 through March 24, 1999

2000 Model Year Vehicles

- Cuautitlan Assembly Plant from December 1, 1999 through August 11, 2000

NON-COMPLIANCE

During production, the Important Engine Information Label, was not applied to the engine valve cover. Important Engine Information Labels were applied to the hood of these vehicles as a courtesy copy, however, U.S. Federal regulations require that labels be applied to the engine.

SERVICE ACTION

Owners of the affected vehicles will be mailed a supplemental Important Engine Information Label, and instruction sheet showing where the label should be placed. At no charge, owners may choose to have the dealer install the label.

© Copyright 2001 Ford Motor Company


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: ……..1-800-423-8851
Other (Dealer Only) Program Questions: ……1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Field Service Action 02L08
Certain 1999/2000 Model Year F Series Vehicles over 8500 GVWR with 5.4L/6.8L engine
Important Engine Information Label

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

© Copyright 2001 Ford Motor Company

Field Service Action 02L08
Certain 1999/2000 Model Year F Series Vehicles Over 8500 GVWR with 5.4L/6.8L engine
Important Engine Information Label

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install supplemental Important Engine Information Label.	02L08B	0.2 Hours

PARTS REQUIREMENTS

Ordering Instructions for Additional Labels

Important Engine Information Labels for this program are being sent directly to owners of the affected vehicles. Additional labels may be ordered at no charge by calling the Special Service Support Center at 1-800-325-5621. Inform the operator you are calling in regard to Field Service Action 02L08. Be prepared to provide your name, address, dealer P & A code, and the label code (shown in NAVIS) needed for the individual vehicle.

© Copyright 2001 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

02L08 February 2002

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company has determined that certain 1999/2000 Model Year F Series Vehicles, over 8500 GVWR with 5.4L/6.8L engine, fail to conform to the requirements specified in the Federal Emissions Standard which requires that vehicles over 8500 GVWR, need an Important Engine Information Label affixed to the engine.

The Important Engine Information label was inadvertently left off the engine during production. Although this does not affect your vehicle's operation, we are required to provide you with the Important Engine Information Label for the engine. We apologize for this inconvenience and want to assure you that we are dedicated to correcting this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…

All vehicles over 8500 GVWR are required to have an Important Engine Information Label fitted to the engine.

What *Ford Motor Company* and your dealer will do…

If the Important Engine Information label is missing from the passenger side engine valve cover, please attach the enclosed Emission Label. To install the label yourself, use the instructions provided with this letter. If you prefer, your Ford or Lincoln Mercury dealer will install the label for you at no charge.

If you wish to have your dealer install the label, call your dealer and request an appointment to have Field Service Action 02L08 performed on your vehicle. On your appointment date bring this letter and the label to your dealer.

If you lose your label, let your dealer know when you request an appointment, so another label can be ordered.

This program will expire August 31, 2002.

If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

© Copyright 2001 Ford Motor Company

If you've changed address or sold the vehicle...

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner.

If you have questions…

If you have questions or need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Hearing impaired call (800) 232-2952. TDD for the hearing impaired.

Or you may contact us through the Internet …

www.ownerconnection.com

If you are still having trouble getting your vehicle repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.


Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. We stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,




Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

IMPORTANT ENGINE INFORMATION (IEI) LABEL INSTALLATION

1. The IEI label is to be installed on the passenger side valve cover. Open the hood of the vehicle and locate the area as shown in the illustration.



2. Using isopropyl alcohol and a clean cloth, clean the area and allow it to dry.
3. Remove the backing material from the ***new*** label and apply the label in the area specified.
4. Smooth the label as you apply it to remove bubbles or wrinkles.

Ford Motor Company
CPR © 2002 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
01/02