ELECTRICAL—POWER WINDOW—REAR POWER WINDOW INOPERATIVE—VEHICLES BUILT THROUGH 1/22/2002	Article No. 02-7-3

LINCOLN: 2000-2002 LS

This article is being republished in its entirety to update the vehicle applications and the parts involved.

ISSUE

The rear door power window regulator may become inoperative, leaving the customer unable to raise or lower the rear window glass. This may be caused by the rear window regulator malfunctioning.

ACTION

If inspection and diagnostics lead to an inoperative rear window regulator, install the revised design window regulators in BOTH rear doors per the procedure in the appropriate model year Lincoln LS Workshop Manual, Section 501-11 (Window Regulator - Rear Door - Removal and Installation).

PART NUMBER	PART NAME
2W4Z-5427008-AA	Window Regulator - RH
2W4Z-5427009-AA	Window Regulator - LH

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-1-2
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 102000

Copyright © 2002 Ford Motor Company