Ford Motor Company

Service Recall Bulletin

May 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S09: Certain 2000 Model Year Crown Victoria and Grand Marquis – Windshield Wiper Control Module Replacement

AFFECTED VEHICLES

Certain 2000 model year Crown Victoria and Grand Marquis vehicles built at the St. Thomas Assembly Plant from March 26, 2000 through April 28, 2000.

SAFETY CONCERN

The windshield wipers in the affected vehicles may become inoperative under excess load conditions (such as snow, ice, and debris) due to insufficient electrical carrying capacity in the wiper control module circuitry. Inoperative windshield wipers may reduce driver visibility during inclement weather and dirty conditions.

SERVICE ACTION

Dealers will inspect the wiper control module and if necessary replace it with a redesigned module. Do not demonstrate or deliver any vehicles affected by this recall until the wiper control module has been inspected and if necessary, a new module installed.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other (Dealer Only) Recall Questions: 1-800-325-5621

Sincerely,

Ann O'Neill
Director

Vehicle Service and Programs

DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S09:
Certain 2000 Model Year Crown Victoria and Grand Marquis
Windshield Wiper Control Module Replacement

OASIS

OASIS will be activated for this recall Tuesday May 9, 2000. You must use OASIS to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

RENTAL CARS

Rental cars are not authorized for this recall.

DEMONSTRATION / DELIVERY HOLD - Safety Recall 00S09:
Certain 2000 Model Year Crown Victoria and Grand Marquis
Windshield Wiper Control Module Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Wiper Control Module for Green Dot.	00S09A	0.2 Hours
Inspect and Replace Wiper Control Module	00S09B	0.4 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Seed Stocking of the wiper control modules will begin the week of May 15, 2000 and will continue for the next several weeks until 75% of each dealer's "Affected Unit Volume" has been shipped. The first seed stock shipment will be sent as an Interim Order. All other seed stock orders will be sent with your weekly Stock Order. After June 16, 2000, dealers should order parts through normal order processing channels.

Service part orders for this wiper control module on vehicles **not** affected by this recall must be ordered through the Recall Hotline at 1-800-325-5621 until June 16, 2000.

There are approximately 23,000 total vehicles involved in this recall.

Part Number	Description	Quantity
F3LY-17C476-C	Wiper Control Module	1

ORDER INFORMATION DOR/COR

DOR/COR number 50160 identifies parts ordered for this campaign through the following:

- Seed Stock Program
- Recall Hotline (1-800-325-5621)

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

DEMONSTRATION / DELIVERY HOLD: Safety Recall 00S09
Certain 2000 Model Year Crown Victoria and Grand Marquis
Windshield Wiper Control Module Replacement

Refer to the 2000 Crown Victoria and Grand Marquis workshop manual Group 5 Section 501 for wiper control module location and replacement instructions.

INSPECTION PROCEDURE

The module must first be inspected for a **green dot** to determine if replacement is required. Modules that have a green dot have been updated at the assembly plant and do **NOT** require replacement.

1. Open the ashtray and look between the dash panel and the ashtray at the visible face of the wiper control module.
2. Inspect the module for a green dot (sticker). If necessary, shine a flashlight from under the dash panel to illuminate the module. If the module has a green dot, do not replace the module and return the vehicle to the customer. Replace the module if there is no green dot.

MODULE REPLACEMENT PROCEDURE

Refer to the 2000 Crown Victoria and Grand Marquis workshop manual Group 5 Section 501 for wiper control module replacement instructions.

Bracket Transfer

The module bracket must be transferred from the old module to the *new* module. The bracket is held in place by two round retaining buttons; depress the buttons simultaneously and slide the bracket off the old module. The bracket will lock into place automatically when it is slid onto the *new* module.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

May, 2000

00S09

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect that relates to motor vehicle safety exists in certain 2000 Crown Victoria and Grand Marquis vehicles built from March 26, 2000 through April 28, 2000.

We apologize for this situation and want to assure you that with your assistance we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the safety issue is…	The windshield wipers in the affected vehicles may become inoperative under excess load conditions (such as snow, ice, and debris) due to insufficient electrical carrying capacity in the wiper control module circuitry. Inoperative windshield wipers may reduce driver visibility during inclement weather and dirty conditions.
What Ford Motor Company and your dealer will do...	Ford Motor Company will inspect the wiper control module in your vehicle and if necessary replace it with a redesigned module free of charge. Owners who are affected by this recall are requested to return their vehicle to their dealer for this service.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.
What we are asking you to do…	Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 00S09. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering. When you bring your vehicle in, show the dealer this letter. If you

misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director

Vehicle Service and Programs