TRANSAXLE—AX4S—REPLACEMENT APPLICATION CHART—WINDSTAR VEHICLES ONLY	Article No. 01-17-1

FORD: 1995-2000 WINDSTAR

ISSUE

Remanufactured transaxle application charts for the 1995-2000 Windstar vehicles with an AX4S transaxle have been published with conflicting information. This article contains an application chart that should be used when ordering a transaxle for Windstar vehicles.

ACTION

When ordering a remanufacture transaxle for a 1995-2000 Windstar vehicle refer to the application chart in Figure 1.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000, 502000, 503000, 503300, 504000

MODEL YEAR	VEHICLE	ENGINE	ENGINEERING PART NUMBER	TRANSAXLE MODEL NUMBER	SERVICE PART NUMBER
1995	WINDSTAR	3.0L 2V VULCAN	F58P-7000-AA	PNA-WA	F58Z-7000-ARM
1995	WINDSTAR	3.8L 2V V6	F48P-7000-BA	PNA-WB	F48Z-7000-BRM
1995	WINDSTAR	3.8L 2V V6	F48P-7000-BB	PNA-WB	F48Z-7000-CRM
1996	WINDSTAR	3.0L 2V VULCAN	F68P-7000-BA	PNA-WA	F68Z-7000-BARM
1996	WINDSTAR	3.8L 2V V6 SPI	F68P-7000-AA	PNA-WC	F68Z-7000-AARM
1997	WINDSTAR	3.0L 2V VULCAN	F68P-7000-BA	PNA-WA	F68Z-7000-BARM
1997	WINDSTAR	3.8L 2V V6 SPI	F68P-7000-AA	PNA-WC	F68Z-7000-AARM
1998 BUILT BEFORE 9/9/97	WINDSTAR WITH F78P AX4S	3.0L 2V VULCAN	F78P-7000-AA	PNA-WA	F78Z-7000-ARM
1998 BUILT BEFORE 9/9/97	WINDSTAR WITH F78P AX4S	3.8L 2V V6 SPI	F78P-7000-BA	PNA-WC	F78Z-7000-BRM
1998 BUILT ON/AFTER 9/9/97	WINDSTAR WITH F88P AX4S	3.0L 2V VULCAN	F88P-7000-AA	PNA-WE1	F88Z-7000-AARM
1998 BUILT ON/AFTER 9/9/97	WINDSTAR WITH F88P AX4S	3.8L 2V V6 SPI	F88P-7000-BA	PNA-WF1	F88Z-7000-BARM
1999	WINDSTAR	3.0L 2V VULCAN	XF2P-7000-AA	PNA-WA	XF2Z-7000-AARM
1999	WINDSTAR	3.8L 2V V6 SPI	XF2P-7000-BA	PNA-WC	XF2Z-7000-BARM
2000	WINDSTAR	3.0L 2V VULCAN	YF2P-7000-AA	PNA-WJ	YF2Z-7000-AARM
2000	WINDSTAR	3.8L 2V V6 SPI	YF2P-7000-BA	PNA-WK	YF2Z-7000-BARM

TB- 6437-A

Figure 1 - Article 01-17-1

Copyright © 2001 Ford Motor Company