AXLE—REAR AXLE SHAFT AND/OR BEARING PREMATURE WEAR—TOWN CAR LIVERY AND CROWN VICTORIA TAXI/POLICE MODELS ONLY

Article No. 02-25-3

FORD: 2003 CROWN VICTORIA

LINCOLN: 2003 TOWN CAR

ISSUE

Some Town Car Livery and Crown Victoria Taxi and Police vehicles may exhibit rear axle shaft and/or bearing premature wear. This is caused by excessive load, temperature and inadequate lubrication.

ACTION

To service, install Axle Bearing service kit part number 3W1Z-4A109-AA. Refer to the instruction sheet included with the service kit.

PART NUMBER	PART NAME
3W1Z-4A109-AA	Rear Axle Bearing Service Kit

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022503A	Install Axle Bearing Service Kit	1.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
4234	42

OASIS CODES: 509000, 510000, 703200, 703300

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company