Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

May 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Owner Notification Program 01B75: Certain 2001 Model Year U. S. Postal Service Explorer 4x4 Vehicles – Front Axle Bolt and Washer Inspection

OASIS : Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until November 30, 2001, regardless of mileage. (After this program expires, the vehicle may still be eligible for this service under any remaining vehicle warranty coverage.)

AFFECTED VEHICLES

Certain 2001 model year USPS Explorer 4x4 vehicles built at the Detroit Chassis Plant from July 18, 2000 through November 28, 2000.

REASON FOR PROGRAM

In some of the affected vehicles, an incorrect bolt and washer may have been inadvertently installed in the front axle. If the incorrect bolt and washer were installed, it may be possible for it to become loose and fall out, causing loud noises and vibration under the front end of the vehicle.

SERVICE ACTION

The dealer must inspect the front axle bolts on all of the affected vehicles. The correct bolt(s) and a new nut(s) will be installed if the incorrect bolt(s) was installed or if a bolt is missing.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other Program Questions:……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 01B75
Certain 2001 Model Year USPS Explorer 4x4 vehicles
Front Axle Bolt and Washer Inspection

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on your dealer Recall/ONP Involved Unit Listings available on QCDealer.com. Also, correct other eligible vehicles that are brought to your dealership.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

Program Code:	01B75
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hour

Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not approved for this program.

Owner Notification Program 01B75
Certain 2001 Model Year USPS Explorer 4x4 vehicles
Front Axle Bolt and Washer Inspection

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect the front axle bolts and washers	01B75A	0.2 Hour
Replace **incorrect** front axle bolts and washers (includes inspection time)	01B75B	0.4 Hour
Install **missing** front axle bolts and washers (includes inspection and test drive time)	01B75C	0.6 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this program. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
N808403-S426	Horizontal Bolt (Package of 2)	1 - 2
N811623-S426	Nut and Retainer (Package of 3)	1 - 3
N811242-S426	Vertical Bolt (Package of 1)	1

Total Involved Population = 1,001 United States Postal Service Explorers. Please refrain from ordering for this campaign unless you are a USPS servicing dealership.

ORDER INFORMATION DOR/COR

DOR/COR number 50238 identifies parts ordered for this campaign through the Special Service Support Center (1-800-325-5621).

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

May 2001

01B75

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service, Program Number 01B75, to owners of certain 2001 model year USPS Explorer 4x4 vehicles.

Reason For This Program

In some of the affected vehicles, an incorrect bolt and washer may have been installed in the front axle. If the incorrect bolt and washer were installed, it may be possible for it to become loose and dislodge from the frame causing a loud noise and vibration under the front end of the vehicle.

What Ford Motor Company and your dealer will do…

The dealer must inspect the front axle bolts on all of the affected vehicles. If the incorrect bolt(s) is present or the bolt(s) is missing, it must be replaced.

This program will be in effect until November 30, 2001, regardless of mileage. (After this program expires, the vehicle may still be eligible for this service under any remaining vehicle warranty coverage.)

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Owner Notification Program 01B75.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

If you have already paid for this service…

If you paid to have this service done before the date of this letter, Ford Motor Company is offering a full refund. To receive a refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance.

If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332…

Hearing impaired, call (800) 232-5952…

Office Hours: (Eastern Standard Time)

Monday - Friday:	8AM – 11PM
Saturday:	9AM – 6PM

TDD for the hearing impaired.

Or you may contact us through the Internet …

www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.



Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs