Ford Motor Company

August 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD – Advance Announcement of Safety Recall 00S19: **ALL** 2001 Model Year Escape Vehicles – Steering Wheel Retention Quality Issue

DO NOT DRIVE, DEMONSTRATE, DELIVER OR PERFORM PRE-DELIVERY INSPECTION ON ANY VEHICLES AFFECTED BY SAFETY RECALL 00S19 UNTIL THE REPAIR HAS BEEN PERFORMED.

AFFECTED VEHICLES

ALL 2001 model year Escape vehicles built at the Kansas City Assembly Plant from April 17, 2000 through July 26, 2000.

REASON FOR THIS DELIVERY HOLD ANNOUNCEMENT

A quality issue has been identified related to the retention of the steering wheel on all 2001 model year Escape vehicles.

Service repair instructions and parts requirements for Safety Recall 00S19 are currently under development.

Additional information, as it becomes available, will be communicated to the dealers via QCDealer.com and via OASIS broadcast messages.

Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to a buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $ 1,100 per vehicle.

Affected vehicles are to be released from this hold only when the appropriate service repair has been completed.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs