ELECTRICAL—REVISED MECHANICAL HOOD LAMP SWITCH TO REPLACE OLD STYLE MERCURY HOOD LAMP SWITCH	Article No. 01-21-6

FORD: 1987-1995 TAURUS
1988-1991 CROWN VICTORIA
1989 THUNDERBIRD
1989-1996 MUSTANG
1994-1996 THUNDERBIRD
1990 BRONCO II
1990-1996 RANGER
1991-1996 BRONCO
1994-2001 EXPLORER
1997-2001 F-150
2000-2001 EXCURSION
2002 EXPEDITION

LINCOLN: 1989-1994 CONTINENTAL
1990-1992 MARK VII
1990-1996 TOWN CAR
1993-1995 MARK VIII
2002 NAVIGATOR

MERCURY: 1987-1995 SABLE
1988-1991 GRAND MARQUIS
1989 COUGAR
1994-1996 COUGAR
1997-2001 MOUNTAINEER

ISSUE

This article is to provide information on replacement hood lamp switches. The 27 degree Mercury style hood switches will no longer be available. Replacement 27 degree Mechanical switches will be available as a service replacement.

ACTION

For vehicles requiring hood lamp switch replacement, replace the 27 degree Mercury switch with new 27 degree Mechanical switch. Replace hood lamp switch per the appropriate model year Workshop Manual as needed.

Old Service Part Number	New Service Part Number
F6TZ-15702-AA E7DZ-15702-A	1U5Z-15702-AA 1U5Z-15702-AA

PART NUMBER	PART NAME
1U5Z-15702-AA	27 degree Mechanical Hood Lamp Switch

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 201000, 201200

Copyright © 2001 Ford Motor Company