Ford Motor Company

A.R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Owner Notification Program 01B81: Certain 1999 and 2000 Model Year F150 Lightning Vehicles - Intercooler Replacement

REF:
- Dealer Announcement dated May 10, 1999, Low Volume Announcement Letter
- Dealer Announcement dated 12/17/98, Special Handling Procedure

OASIS: Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until September 30, 2002, regardless of mileage.

AFFECTED VEHICLES

Certain 1999 and 2000 model year F150 Lightning vehicles built at the Ontario Truck Assembly Plant from the beginning of production for the 1999 model year through the end of production for the 2000 model year.

REASON FOR PROGRAM

In some of the affected vehicles, the supercharger intercooler may fracture and create an internal coolant leak. If this occurs the vehicle may experience loss of engine performance at full throttle.

SERVICE ACTION

Dealers must replace the supercharger's intercooler sub-assembly and top-off the intercooler coolant system on all affected vehicles.

LOW VOLUME PROGRAM

This recall is being processed as a Low Volume Program. This type of field action was announced in an All-Dealer letter dated May 10, 1999.

Owners will be contacting the Low Volume Program Coordination Center to arrange for this service. We will advise you via CuDL (Customer Data Link) of the owners that choose your dealership to perform the service provided by this Low Volume program. The parts will be ordered for you by the Program Coordination Center.

You are requested to contact the owner and arrange for this service. (Note that our Coordination Center will advise owners that they will hear from you within the next two business days of owner contact).

© Copyright 2001 Ford Motor Company

SPECIAL HANDLING PROCEDURE

The Special Handling Procedure has been activated for all Lightning owners affected by this program. Please see dealer announcement dated 12/17/98, Special Handling Procedure. The special handling procedure provides additional allowance to enable dealers to offer Lightning owners convenient vehicle handling.

Ford Motor Company is asking for your support and the cooperation of your sales and service teams to make this a positive experience for our Lightning customers, many of whom are new to the SVT family.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: ……1-800-423-8851
Non-SVT Related Program Questions: ……1-800-325-5621
Ford SVT Questions:……1-800-367-3788
SVT Owner Scheduling:……..1-800-248-0186

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Owner Notification Program 01B81
Certain 1999 and 2000 Model Year F150 Lightning Vehicles
Intercooler Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

You must contact the Low Volume Recall Coordination Center at (1-800-248-0186) to arrange for parts if you have an involved vehicle in stock. When calling this number, identify Owner Notification Program 01B81 and provide the VIN of the dealer stock vehicle to be serviced.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list, but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this field service action is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

When you receive notification through CuDL (Customer Data Link), you should contact the owner and arrange for this service. Please note that our Low Volume Program Coordination Center will advise owners that they will hear from you within the next two business days. For more information, see "Low Volume Announcement Letter" dated May 10, 1999.

Also, Lightning owners should receive the "Special Handling Procedure". Before calling Lightning owners, review the dealer announcement dated 12/17/98 to familiarize yourself with this special handling procedure.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

To claim for the "Special Handling Procedure", follow the instructions on page two of dealer announcement dated 12/17/98.

© Copyright 2001 Ford Motor Company

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the owner letter (or after the date of the owner letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Ford Motor Company will pay for a rental vehicle, except for fuel and insurance, which will be at owner's expense. Enter the word "RENTAL" plus the number of days the vehicle was used in the Miscellaneous Expense area of the claim form.

© Copyright 2001 Ford Motor Company

Owner Notification Program 01B81
Certain 1999 and 2000 Model Year F150 Lightning Vehicles
Intercooler Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Supercharger Intercooler Sub-Assembly	01B81B	2.2 Hrs.
Special Handling:	Misc. Expense Code "LCHP"	See Special Handling Procedure

PARTS REQUIREMENTS

Parts Ordering Information

CUSTOMER VEHICLES:

Parts will be shipped to your dealership according to the procedures established for "Low Volume Recalls." DO NOT order parts, except for dealer stock units (Refer to "Low Volume Recalls").

Note: When the customer calls the Coordination Center, the correct parts will be automatically sent to the dealer.

STOCK VEHICLES:

Correct all vehicles in stock before delivery. First, determine part requirement. Then, contact the Low Volume Program Coordination Center at 1-800-248-0186 to arrange for parts. When calling this number, identify Owner Notification Program 01B81, and have the VIN of the dealer stock vehicle to be serviced.

Parts will not be direct shipped for this program. For stock units, order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
All Order Types	First 90 days after launch	Call 1-800-325-5621
All Order Types	91 days after launch	Normal order process

Part Number	Description	Quantity
XL3Z-9424-AB	Intercooler Sub-Assembly Kit	1
VC-4-A	Premium Engine Coolant (Green)	As Required

***** The amount listed is the maximum coolant amount for claim purpose. Vehicles require coolant to be mixed with an equal amount of water. Total capacity is approximately one gallon.

ORDER INFORMATION

The DOR/COR for this program is 50255. This number identifies parts ordered for this campaign through the Special Service Support Center (1-800-325-5621).

© Copyright 2001 Ford Motor Company

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures.”

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2001 Ford Motor Company