Related Newsletter Articles

01B86 Inspection/Verification – NGS Red Card

12/10/2001

If the technician is using NGS and is unable to perform HEC module identification, have the technician back flash the NGS red card to version 19.0 and retry module identification.

The technician also has the option of using WDS. The WDS version works fine.

Copyright © 2001 Ford Motor Company
Published By: **Recall/Service Programs Department**
Ford Customer Service Division