Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Service Instruction 00T07: All 1999 and 2000 MY Windstar Vehicles - PCM Reprogram

OASIS : Yes
OWNER LIST: **No**
OWNER LETTERS: **No**
PARTS RETURN: n/a
PROGRAM TERMS: Through applicable new vehicle warranty coverage only

AFFECTED VEHICLES

All 1999 and 2000 model year Windstar vehicles built at the Oakville Assembly Plant from Job #1 through July 25, 2000.

REASON FOR THIS SPECIAL SERVICE INSTRUCTION

Some of the affected vehicles were built with a Powertrain Control Module (PCM) calibration strategy that may cause the vehicle to exhibit reduced battery charging performance.

SPECIAL SERVICE INSTRUCTION

The vehicle's PCM must be reprogrammed using the Worldwide Diagnostic System (WDS) or the New Generation Star Tester (NGS).

NOTE: Reprogramming the PCM using program code 00T07 is the only authorized service chargeable to this Special Service Instruction. This service involves the reprogramming of the Powertrain Control Module (PCM) without diagnosis. Any diagnostic trouble codes (DTCs) must be diagnosed before reprogramming the PCM and are not chargeable to this program. Claims submitted with any additional service or related damage will be rejected.

OWNER NOTIFICATION

There will be no owner notification from Ford Motor Company. This Special Service Instruction is part of applicable emissions warranty service. Dealers should inform owners upon completion of this Special Service Instruction that their vehicle's PCM was reprogrammed as a calibration upgrade to improve driveablity and customer satisfaction.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances
Attachment III: Technical Information

QUESTIONS?

Claims Information: 1-800-423-8851
Other Program Questions: 1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

SPECIAL SERVICE INSTRUCTION: 00T07
All 1999 and 2000 Model Year Windstar - PCM Reprogram

OASIS

You must use OASIS to determine if a vehicle is eligible for this Special Service Instruction.

PLEASE NOTE

Correct all vehicles in stock before delivery.

PROMPTLY CORRECT

Promptly correct all affected vehicles at your dealership and other eligible vehicles which are brought to your dealership within the applicable new vehicle warranty time and mileage.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.

NOTE: Prepare and submit claims on the ACESII **warranty** screen rather than the ACESII recall screen.

- Use code information shown below:
    - Program Code – 00T07
    - Casual Component – RECAL
    - Condition Code – 42
    - Labor Operation – Refer to Attachment II

SPECIAL SERVICE INSTRUCTION: 00T07
All 1999 and 2000 MY Windstar Vehicles - PCM Reprogram

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Check PCM Calibration - Latest Level Already Installed	00T07A	0.3 Hours
Reprogram PCM and Affix Modification Label	00T07B	0.4 Hours

PARTS REQUIREMENTS

Part Number	Quantity	Description
FPS-8262	1	Authorized Modifications Label (Free to Dealers)